

**Status Report**

**PC-12/45**  
**S/N 498 OH-MUG**

**OWNER:** MUGABURU SL  
**ADDRESS:** -  
**PHONE:**  
**FAX:**

**OPERATOR:** FLY 7 FINLAND OY  
**ADDRESS:** LIIKELENTOTIE 8  
VANTAA 01530  
**PHONE:** +358 40 594 3022  
**FAX:**

**OPERATOR:** FLY 7 EXECUTIVE AVIATION SA  
**ADDRESS:** AEROPORT DE LAUSANNE  
LAUSANNE CH-1018  
**PHONE:** +41 21 648 21 42 (OPS)  
**FAX:** +41 21 648 21 43

**ANALYST:** ADRIEN LIMMELETTE +33 1.55.93.47.77 (DIRECT)  
**EMAIL:** ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)  
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS;

**AIRCRAFT SERIAL/REGNO:** 498/OH-MUG **MODEL:** PC-12/45 **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 23-MAY-2003	3734:55 A/C HRS as of 16-MAY-2021	A/C HRS as of ___/___/___
	3080 AFL as of 16-MAY-2021	AFL as of ___/___/___
	495:12 ACH as of 22-JAN-2021	ACH as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** PCE-PR0368/3042200 **MODEL:** PT6A-67B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 26-MAY-2003	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 0 A/C HRS	3734:55 ENG. HRS as of 16-MAY-2021	ENG. HRS as of ___/___/___
0 ENC	3002 ENC as of 16-MAY-2021	ENC as of ___/___/___

**PROPELLER NO SERIAL/PART:** 150403/MTV-27-1-N-C-F-R(P)/C FR260-65A **MODEL:** MTV-27-1-N-C-F-R(P)/CFR260-65A **MANUFACTURER:** MT-PROPELLER

INSTALLED ON 04-DEC-2015	LAST ACTUALS	CURRENT ACTUAL
0 PROP HRS 2873:15 A/C HRS	861:40 PROP HRS as of 16-MAY-2021	PROP HRS as of ___/___/___



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>							
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 15 in PKG 16,17,18,19,20,21	MOS				10-FEB-2021	PKG	
	REF: AMM	HRS/MSC	A/R			3700:03		
	12-A-05-20-00-00A-913A-A	AFL				3030		
05401A	300 HOUR INSPECTION							
+	PKG 16	MOS				10-FEB-2021		
	REF: AMM	HRS/MSC	300	+30/-30		3700:03	<b>4000:03</b>	4030:03
	12-A-05-40-01-01A-000B-A	AFL				3030		
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+	PKG 17	MOS	12	+1m/-1m	10	10-FEB-2021	<b>20-FEB-2022</b>	20-MAR-2022
	REF: AMM	HRS/MSC	300	+30/-30		3700:03	<b>4000:03</b>	4030:03
	12-A-05-40-01-02A-000B-A	AFL				3030		
05403A	600 HOUR INSPECTION							
+	PKG 18	MOS				06-MAR-2020		
	REF: AMM	HRS/MSC	600	+10%/-10%		3576:24	<b>4176:24</b>	4236:24
	12-A-05-40-01-03A-000B-A	AFL				2920		
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+	PKG 19	MOS	12	+1m/-1m	10	10-FEB-2021	<b>20-FEB-2022</b>	20-MAR-2022
	REF: AMM	HRS/MSC	600	+30/-30		3700:03	<b>4300:03</b>	4330:03
	12-A-05-40-01-04A-000B-A	AFL				3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTHS INSPECTION							
+								
	PKG 20	MOS	12			10-FEB-2021	<b>20-FEB-2022</b>	20-MAR-2022
		HRS/MSC	1200			3700:03	<b>4900:03</b>	4930:03
	REF: AMM	AFL				3030		
	12-A-05-40-01-05A-000B-A							

05406A	2400 HOUR OR 24 MONTHS INSPECTION							
+								
	PKG 21	MOS	24			06-MAR-2020	<b>20-FEB-2022</b>	20-MAR-2022
		HRS/MSC	2400			3576:24	<b>5976:24</b>	6006:24
	REF: AMM	AFL				2920		
	12-A-05-40-01-06A-000B-A							

ENGINE NO. 1	Model : PT6A-67B/-67P	Serial # PCE-PR0368	Part # 3042200					
057010	NO. 1 ENGINE - MINOR INSPECTION							
+								
	PKG 2	MOS				10-FEB-2021		
		HRS/MSC	300			3700:03	<b>(4000:03) 4000:03</b>	4030:03
	REF: See Workcard	ENC				2960		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
+ 00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
		HRS/MSC	A/R					3700:03	
	REF:	AFL						3030	
+ 00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
		HRS/MSC	A/R					3700:03	
	REF: GENERIC NO REF	AFL						3030	
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
		HRS/MSC	A/R					3700:03	
	REF: GENERIC NO REF	AFL						3030	
PC12-151203	REVIEW AMM 02049 12-A-AM- REVISION 29, DATED 14 NOV 2014-RCF								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	AFL							
PC12-151204	REVIEW PILATUS AMM, DOC NO. 02049 (12-A-AM-00-00-00-I), REVISION 30, DATED 31 AUG 2015-RCF								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	AFL							
PC12-160717	REVIEW PILATUS PC12 AMM REV 32								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	AFL							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-161212	REVIEW PILATUS PC12 AMM REV 33	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	HRS/MSC - AFL							
PC12-170630	REVIEW PC-12, PC-12/45, PC-12/47 AMM REVISION 34	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	HRS/MSC - AFL							
PC12-170906	REVIEW PC-12, PC-12/45, PC-12/47 AMM TEMPORARY REVISION NO. 05-06	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	HRS/MSC - AFL							
PC12-180209	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 35	MOS						15-MAR-2018	
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	HRS/MSC - AFL							
PC12-180524	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 36	MOS						11-JUL-2018	
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	HRS/MSC - AFL							
PC12-180917	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TEMPORARY REVISION NO. 05-07	MOS						18-OCT-2018	
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF PC12	HRS/MSC - AFL							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
PC12-181129	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND CHAPTER 5 REVISION 37	MOS						08-JAN-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF PC12</b>	HRS/MSC - AFL							
PC12-190517	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 38	MOS						17-JUN-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF PC12</b>	HRS/MSC - AFL							
PC12-200515	REVIEW PC-12, PC-12/45, PC-12/47, AIRCRAFT MAINTENANCE MANUAL- CHAPTER 4 AND 5 REVISION 39	MOS						03-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF PC12</b>	HRS/MSC - AFL							
PC12-201130	REVIEW PC-12, PC-12/45, PC-12/47 AIRCRAFT MAINTENANCE MANUAL REVISION 40	MOS						18-DEC-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF PC12</b>	HRS/MSC - AFL							
<b>ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200</b>									
E072-150812	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 43.0	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-160421	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.0								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-170213	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.2								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-170222	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14002 REV 24								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-170410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.0								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-170621	NO. 1 ENGINE - REVIEW SB PT6A-72-14002 REV 25								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-170707	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14603 R27								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-170728	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.1								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-170818	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 45.2								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072-170818</b>	MOS HRS/MSC - ENC							
E072-171030	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 46.0								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC							
E072-180409	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.0								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	MOS HRS/MSC - ENC					22-MAY-2018		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-180409-1	NO. 1 ENGINE - REVIEW CODE CHANGE NOT PART FOR REV 47	MOS						14-JUN-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-180528	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.1	MOS						13-JUL-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS						25-SEP-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-181029	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 48.0	MOS						06-DEC-2018	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-190408	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 49.0	MOS						14-MAY-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-190802	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 28	MOS						22-AUG-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-191028	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.0	MOS						23-DEC-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-191205	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 50.1	MOS						16-APR-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-200413	NO. 1 ENGINE - REVIEW PT6A-67B/-67P MM REV 51.0	MOS						11-MAY-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - ENC							
E072-200429	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.1	MOS						11-MAY-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - ENC							
E072-200504	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.2	MOS						04-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-200505	NO. 1 ENGINE - REVIEW PWC SB P6A-72-14001 REV 20	MOS						01-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-200521	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 29	MOS						01-JUN-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-200910	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 51.3	MOS						20-OCT-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-201012	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 52.0	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-201202	NO. 1 ENGINE - REVIEW PWC SB PT6A-72-14002 REV 26	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
E072-210412	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 53.0	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E072</b>	HRS/MSC - ENC							
<b>PROPELLER NO. 1 Model : MTV-27-1-N-C-F-R(P)/CFR260-65A Serial # 150403 Part # MTV-27-1-N-C-F-R(P)/CFR260-65A</b>									
P605-150629	NO. 1 PROPELLER - REVIEW MT-PROPELLER, OPERATION AND INSTALLATION MANUAL (E-1083) REVISION 23, DATED MAY 28, 2015-RCF	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>	HRS/MSC -							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P605-160208	NO. 1 PROPELLER - REVIEW MT PROPELLER, MTV-27-1-N-C-F-R /CFR260-65A (P/N E-1083), OPERATION AND INSTALLATION MANUAL, REVISION NO. 24, DATED FEBRUARY 08' 2016								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605-160208</b>								
P605-160503	NO. 1 PROPELLER - REVIEW MT PROPELLER, MTV-27-1-N-C-F-R /CFR260-65A (P/N E-1083), OPERATION INSTALLATION MANUAL, REV24-RCF								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>								
P605-160812	NO. 1 PROPELLER - REVIEW MT-PROPELLER MTV-27-1-N-C-F-R(P)/CFR260-65A OPERATION AND INSTALLATION MANUAL (E-1083) REVISION 25								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>								
P605-160901	NO. 1 PROPELLER - REVIEW MT-PROPELLER MTV-27-1-N-C-F-R(P)/CFR260-65A OPERATION AND INSTALLATION MANUAL (E-1083) REVISION 26								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605-160901</b>								
P605-161129	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A SB1 R1 SUPP2								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>								
P605-161510	NO. 1 PROPELLER - REVIEW MT-PROPELLER, MTV-27-1NCFR(P)-CFR260-65A, SUP 1 TO SB 1R1								
		MOS							
		HRS/MSC	-						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>								

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P605-170119	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A REV 26	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P605	HRS/MSC -							
P605-170317	NO. 1 PROPELLER - REVIEW MT PROPELLERS MTV-27-1-N-C-F-R(P)/CFR260-65A SB1 R2	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P605	HRS/MSC -							
P605-170329	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A OMM REV 27	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: See Workcard	HRS/MSC -							
P605-180706	NO. 1 PROPELLER - REVIEW SERVICE BULLETIN NO. 1 R3	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: See Workcard	HRS/MSC -							
P605-181113	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A OMM REV 28	MOS					12-DEC-2018		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P605	HRS/MSC -							
P605-181203	NO. 1 PROPELLER - REVIEW SERVICE BULLETIN NO. 1 R3 SUPP 1	MOS					08-JAN-2019		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P605	HRS/MSC -							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P605-190108	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A SB1 R4	MOS						14-FEB-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>	HRS/MSC -							
P605-190226	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A OMM REV 29	MOS						04-APR-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>	HRS/MSC -							
P605-190411	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A OMM REV 30	MOS						11-OCT-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>	HRS/MSC -							
P605-191018	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A OMM REV 31	MOS						20-NOV-2019	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>	HRS/MSC -							
P605-200309	NO. 1 PROPELLER - REVIEW MT PROPELLER SERVICE BULLETIN NO. 1 R5	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>	HRS/MSC -							
P605-200409	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A OMM REV 32	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF P605</b>	HRS/MSC -							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P605-201130	NO. 1 PROPELLER - REVIEW MTV-27-1-N-C-F-R(P)/CFR260-65A OMM REV 33	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P605	HRS/MSC -							
P605-210427	NO. 1 PROPELLER - REVIEW MT PROPELLER SERVICE BULLETIN NO. 1 R6	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF P605	HRS/MSC -							
	NEW REQUIREMENT ADDED ON 12-MAY-2021 (EFFECTIVE: 27-APR-2021). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

## CHAPTER 04 LIMITATIONS

+ 040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			23-MAY-2003		
	SN-UNKNOWN	HRS/MSC	50000	N:0			0		50000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	60000	N:0			0		60000
040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			23-MAY-2003		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	43000	N:0			0		43000
040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			23-MAY-2003		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL	43000	N:0			0		43000

## CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

+ 050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)								
		MOS					23-MAY-2003		
		HRS/MSC	25000				0		25000
	REF: AMM 05-10-30	AFL	30000				0		30000

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					23-MAY-2003		
		HRS/MSC	25000				0	25000	
	REF: GENERIC NO REF	AFL	30000				0	30000	
05ARC00	AIRWORTHINESS REVIEW CERTIFICATE (ARC)	MOS	12				29-MAR-2021	05-APR-2022 M	
		HRS/MSC					3708		
	REF:	AFL							
<b>CHAPTER 06 DIMENSIONS AND AREAS</b>									
+ 06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					10-FEB-2021		
		HRS/MSC	A/R				3700:03		
	REF: AMM 06-20-00	AFL					3030		
+ 06-00/123	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					10-FEB-2021		
		HRS/MSC	A/R				3700:03		
	REF: AMM 06-20-00	AFL					3030		
+ 06-00/218 (s)	OPEN AND REMOVE AS NECESSARY TO DO INSPECTION ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 12GZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB OPEN/REMOVE AND EXAMINE. MAKE SURE THE DRAIN HOLES ARE CLEAR.						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					10-FEB-2021		
		HRS/MSC	A/R				3700:03		
	REF: AMM 06-20-00	AFL					3030		
+ 06-00/219 (s)	CLOSE ACCESS PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 12GZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB CLOSE OR INSTALL						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					10-FEB-2021		
		HRS/MSC	A/R				3700:03		
	REF: AMM 06-20-00	AFL					3030		

**CHAPTER 07 LIFTING AND SHORING**



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				10-FEB-2021 3700:03 3030		
+ 07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND PKG 15 ,16,17,18,19,20,21 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				10-FEB-2021 3700:03 3030		
<b>CHAPTER 08</b>	<b>LEVELING AND WEIGHING</b>								
080000	WEIGHT AND BALANCE REF:	MOS HRS/MSC AFL	48	+10%/-10%			16-FEB-2018 3195:20 2528	<b>16-FEB-2022</b>	10-JUL-2022
<b>CHAPTER 10</b>	<b>PARKING, MOORING, STORE AND RET TO SERV</b>								
+ 10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY. PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			10-FEB-2021 3700:03 3030		
<b>CHAPTER 11</b>	<b>PLACARDS AND MARKINGS</b>								
+ 11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			10-FEB-2021 3700:03 3030		
<b>CHAPTER 12</b>	<b>SERVICING</b>								
+ 12-20/124 (s)	WASH AIRCRAFT EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-01	MOS HRS/MSC AFL	A/R				10-FEB-2021 3700:03 3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-02	MOS HRS/MSC AFL	A/R				PKG 10-FEB-2021 3700:03 3030		
+ 12-20/126 (s)	CLEAN COCKPIT AND CABIN PKG 15 ,16,17,18,19,20,21 REF: AMM 12-20-03	MOS HRS/MSC AFL	A/R				PKG 10-FEB-2021 3700:03 3030		
<b>CHAPTER 20 STANDARD PRACTICES - AIRFRAME</b>									
+ 00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL) 20.010 REF: AMM 20-40-00	MOS HRS/MSC AFL	12	+1m/-1m	-4		10-FEB-2021 3700:03 3030	<b>06-FEB-2022</b>	06-MAR-2022
+ 00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL) 20.011 REF: AMM 20-40-00	MOS HRS/MSC AFL	6	+10%/-10%			10-FEB-2021 3700:03 3030	<b>10-AUG-2021</b>	28-AUG-2021
+ 00-00/45C	CORROSION INSPECT (AND ONLY APPLICABLE IF IN SEVERE CLIMATIC CONDITION) 20.015 REF: AMM 20-40-00	MOS HRS/MSC AFL	A/R						
<b>CHAPTER 21 AIR CONDITIONING</b>									
+ 21-20/127 (s)	OPERATIONAL TEST ECS EMERGENCY SHUT-OFF SYSTEM ECS EMER SHUT-OFF VALVE - OPERATIONAL TEST; MAX PULL FORCE 22.5 LBF (100N) AND MAKE SURE RAM AIR SCOOP IS COMPLETELY OPEN PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+10%/-10%			10-FEB-2021 3700:03 3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
		HRS/MSC	2400	+10%/-10%			3576:24		
	REF: GENERIC NO REF	AFL					2920		
+ 21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURIZATION SYSTEM								
	<b>CMT ITEM</b>								
21.040		MOS	24	+10%/-10%	-4		10-FEB-2021	<b>06-FEB-2023</b>	18-APR-2023
		HRS/MSC	3000	+10%/-10%			3700:03	<b>6700:03</b>	7000:03
	REF: AMM 21-30-00	AFL					3030		
+ 21-30/47	REMOVE/CLEAN PRESSURIZATION OUTFLOW VALVE AND SAFETY VALVE. CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN								
	<b>CMT ITEM</b>								
21.030		MOS	24	+10%/-10%	-4		10-FEB-2021	<b>06-FEB-2023</b>	18-APR-2023
		HRS/MSC	3000	+10%/-10%			3700:03	<b>6700:03</b>	7000:03
	REF: AMM 21-30-01	AFL					3030		
+ 21-30/48	FUNCTIONAL TEST CABIN ALTITUDE SWITCH								
21.010		MOS	60	+10%/-10%			20-FEB-2018	<b>15-MAR-2023</b>	15-SEP-2023
		HRS/MSC					3195:20		
	REF: AMM 21-30-07	AFL					2528		
+ 21-30/49	FUNCTIONAL TEST CABIN DIFFERENTIAL PRESSURE SWITCH								
21.020		MOS	60	+10%/-10%			20-FEB-2018	<b>15-MAR-2023</b>	15-SEP-2023
		HRS/MSC					3195:20		
	REF: AMM 21-30-08	AFL					2528		
+ 21-40/128	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH								
		MOS					20-FEB-2018		
		HRS/MSC	N/A				3195:20		
	REF: AMM 21-40-11	AFL					2528		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER						PKG		
21.080	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: AMM 21-40-02	AFL					3030		
+ 21-40/51	FUNCTIONAL TEST OVERTEMPERATURE SWITCH								
21.130		MOS	60	+10%/-10%	23		20-FEB-2018	15-MAR-2023	15-SEP-2023
		HRS/MSC	4800	+10%/-10%			3195:20	7995:20	8475:20
	REF: AMM 21-40-06	AFL					2528		
+ 21-40/52	FUNCTIONAL TEST DUCT OVERTEMPERATURE SWITCH								
21.120		MOS	60	+10%/-10%	23		20-FEB-2018	15-MAR-2023	15-SEP-2023
		HRS/MSC	4800	+10%/-10%			3195:20	7995:20	8475:20
	REF: AMM 21-60-05	AFL					2528		
+ 21-40/53	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 101-320 WITHOUT A MODIFIED AUXILIARY HEATING SYSTEM)								
		MOS					06-FEB-2017		
		HRS/MSC	N/A				3075:06		
	REF: AMM 21-40-09	AFL					2449		
+ 21-40/54 (s)	OPERATIONAL TEST SECONDARY HEATERS THERMAL PROTECTION SWITCHES (MSN 321-999 AND AIRCRAFT WITH A MODIFIED AUXILIARY HEATING SYSTEM)						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: AMM 21-40-00	AFL					3030		
+ 21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 18	MOS					06-MAR-2020		
		HRS/MSC	600	+10%/-10%			3576:24		
	REF: AMM 21-40-01	AFL					2920		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 18 REF: AMM 21-40-01	MOS HRS/MSC AFL	600	+10%/-10%			06-MAR-2020 3576:24 2920		
+ 21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) COOLING UNIT						PKG		
	PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			10-FEB-2021 3700:03 3030		
+ 21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE VAPOR CYCLE COMPRESSOR CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)								
	959.90.22.102 480 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%	10		10-FEB-2021 3700:03 3030	20-FEB-2022 4000:03	20-MAR-2022 4030:03
+ 21-50/461	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	959.90.22.102 480 REF: AMM 21-50-03	MOS HRS/MSC AFL	N/A						
+ 21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	959.90.22.102 480 REF: See Workcard	MOS HRS/MSC AFL	N/A						
+ 21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	959.90.22.102 480 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	500	+10%/-10%			0	500	550

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE BELT TENSION (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.100	959.90.22.102 480 REF: See Workcard	MOS HRS/MSC AFL ACH	500	+10%/-10%			0	500	550
210005	OVERPRESSURE SWITCH								
21.340	973.81.15.105 0285 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210010	REFRIGERATION PACK								
21.255	959.90.20.111 1046 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210015	WATER INJECTOR								
21.370	959.90.20.141 1022 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210020	DUCT TEMP SENSOR								
21.320	959.90.20.121 1036 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210025	PRIM SHUT OFF VALVE								
21.290	959.90.20.132 1016 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210030	HP SHUT OFF VALVE								
21.280	959.90.20.131 1018 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210035	WATER SEPARATOR ASSY								
21.220	521.41.12.060 2156 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210040	TEMPCONTROL VALVE								
21.310	959.90.20.136 1011 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210045	AIR-CONDITIONING - COMPRESSOR / CONDENSER MODULE								
21.380	959.90.22.102 480 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	959.90.22.116 752 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210053	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	959.90.22.115 418 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	959.90.22.116 751 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	959.90.91.121 92-A0429 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	959.90.91.131 43-B0451 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210070	AUXILIARY VOLUME TANK								
21.390	959.90.91.111 102-7556 REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210075	CHECK VALVE								
21.400	959.90.91.151 92-A0491 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210080	JET PUMP								
21.410	959.90.91.161 82-1755 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210085	MANUAL CONTROLLER								
21.420	959.90.91.101 101-A0381 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	959.90.91.141 72-G0425 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210095	CABIN DIFFERENTIAL PRESSURE (ALT/PX) INDICATOR								
21.245	965.23.23.202 1019795 REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210100	CAB RATE INDICATOR								
21.440	965.16.21.002 1022627 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210105	CABIN DIFFERENTIAL PRESSURE SWITCH								
21.330	965.23.21.532 1020431 REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210110	CABIN PX SWITCH								
21.360	965.23.21.531 1020421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	969.67.81.507 502920 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210120	BAY TEMP SENSOR								
21.450	959.90.20.122 1021 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210125	OUTSIDE CABIN TEMPERATURE AIR TEMPERATURE INDICATOR								
21.460	975.15.16.101 A5195 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210130	TEMP CONTROLLER								
21.235	959.90.20.123 1017 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210140	SOLENOID VALVE								
21.300	963.14.11.001 30218126 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	969.67.81.507 502924 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210150	DUAL FLAPPER 25 IN CHECK VALVE								
21.470	963.30.11.106 0243B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210155	MANUALLY OPR SHUTOFF VALVE								
21.480	963.30.11.002 0265 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210160	CABIN HEATER TEMPERATURE TRANSMITTER								
21.350	975.15.16.104 186 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
210165	UNDERFLOOR HEATER TEMPERATURE TRANSMITTER								
21.260	975.15.16.103 189 REF: AMM 21-40-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210170	OVERPRESSURE SWITCH								
21.340	973.81.15.106 0259 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
<b>CHAPTER 22 AUTO FLIGHT</b>									
+ 22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
		HRS/MSC	2400	+10%/-10%			3576:24		
	REF: GENERIC NO REF	AFL					2920		
+ 22-10/60	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m	-4		10-FEB-2021	<b>06-FEB-2022</b>	06-MAR-2022
		HRS/MSC	1000	+10%/-10%			3700:03	<b>4700:03</b>	4800:03
	REF: AMM 22-10-00	AFL					3030		
+ 22-10/60	SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m	-4		10-FEB-2021	<b>06-FEB-2022</b>	06-MAR-2022
		HRS/MSC	1000	+10%/-10%			3700:03	<b>4700:03</b>	4800:03
	REF: AMM 22-10-00	AFL					3030		
+ 22-10/60	SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m	-4		10-FEB-2021	<b>06-FEB-2022</b>	06-MAR-2022
		HRS/MSC	1000	+10%/-10%			3700:03	<b>4700:03</b>	4800:03
	REF: AMM 22-10-00	AFL					3030		
+ 22-10/60	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK								
22.010		MOS	12	+10%/-10%	-4		10-FEB-2021	<b>06-FEB-2022</b>	12-MAR-2022
		HRS/MSC	1000	+10%/-10%			3700:03	<b>4700:03</b>	4800:03
	REF: AMM 22-10-00	AFL					3030		
+ 22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 22-20-02	AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 16	MOS					PKG		
	REF: AMM 22-20-00	HRS/MSC AFL	300	+10%/-10%			10-FEB-2021 3700:03 3030		
+ 22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 20	MOS	12	+10%/-10%			PKG		
	REF: AMM 22-20-00	HRS/MSC AFL	1200	+10%/-10%			10-FEB-2021 3700:03 3030		
220005	AUTOPILOT MODE CONTROL 985.92.03.121	MOS						23-MAY-2003	
22.160	2202	HRS/MSC	O/C		N:0		0		
	REF: AMM 22-10-05	AFL			N:0		0		
220010	ALTITUDE PRESELECTOR 985.92.03.131	MOS						23-MAY-2003	
22.180	2195	HRS/MSC	O/C		N:0		0		
	REF: AMM 22-10-06	AFL			N:0		0		
220015	AILERON KSA372,065-00056-0056 ACTUATOR 985.92.03.161	MOS						23-MAY-2003	
22.100	5432	HRS/MSC	O/C		N:0		0		
	REF: AMM 22-10-03	AFL			N:0		0		
220020	PITCH KSM375,065-00015-0000 MOUNT 985.92.03.173	MOS						23-MAY-2003	
22.190	9166	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
220025	ELEVATOR KSA372,065-00056-0059 ACTUATOR 985.92.03.161	MOS						23-MAY-2003	
22.110	5433	HRS/MSC	O/C		N:0		0		
	REF: AMM 22-10-02	AFL			N:0		0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220030	RUDDER KSM375,065-00015-0001 MOUNT								
22.200	985.92.03.171 9196 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
220035	RUDDER (KSA372) TRIM ACTUATOR								
22.120	985.92.03.163 5353 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
220040	AILERON KSM375,065-00015-0001 MOUNT								
22.210	985.92.03.171 9197 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
220045	STICK PUSHER SERVO								
22.220	978.61.11.103 1464 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
220050	PITCH TRIM ADAPTER								
22.130	985.92.03.181 1531 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
220055	STICK PUSHER CAPSTAN								
22.140	978.61.11.124 1442 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
220060	STICK SHAKER								
22.230	978.61.11.143 403 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220065	AUTOPILOT COMPUTER								
22.150	522.10.12.053 2390 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
220070	STICK PUSHER COMPUTER								
22.170	975.44.23.104 113476 REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
<b>CHAPTER 23 COMMUNICATIONS</b>									
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
23.020	984.81.10.203 10288 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
23.030	984.81.10.203 10282 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
230020	COMM/NAV 25 KHZ SYSTEM								
23.050	985.99.11.367 11125 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:192 N:3363:06 N:2694			28-MAY-2019 3363:06 2694		
230025	AUDIO SUMMING AMPLIFIER								
23.010	987.81.33.108 120 REF: AMM 23-50-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
230030	AUDIO SELECTOR								
23.040	985.99.11.033 165673 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 24</b>	<b>ELECTRICAL POWER</b>								
+ 24-20/227 (s)	OPERATIONAL TEST AC ELECTRICAL SYSTEM						PKG		
	PKG 20	MOS	12	+10%/-10%				10-FEB-2021	
		HRS/MSC	1200	+10%/-10%				3700:03	
	REF: AMM 24-20-00	AFL						3030	
+ 24-30/131 (s)	EXAMINE AND ADJUSTMENT/TEST GENERATOR 2 DRIVE BELT						PKG		
	PKG 17	MOS	12	+10%/-10%				10-FEB-2021	
		HRS/MSC	300	+10%/-10%				3700:03	
	REF: See Workcard	AFL						3030	
+ 24-30/132 (s)	EXAMINE AND OPERATIONAL TEST BATTERY (BATTERIES - IF 2ND BATTERY INSTALLED)						PKG		
	PKG 17	MOS	12	+10%/-10%				10-FEB-2021	
		HRS/MSC	300	+10%/-10%				3700:03	
	REF: See Workcard	AFL						3030	
+ 24-30/19	STARTER GENERATOR								
	<b>CMT ITEM</b>								
	978.91.23.408	MOS						28-APR-2015	
24.020	P1079	HRS/MSC	1200	+10%/-10%	O:0			2790:20	3990:20 4110:20
<b>OVERHAUL</b>	REF: AMM 24-30-01	AFL			O:0			2233	
+ 24-30/21	GENERATOR 2 DRIVE ASSEMBLY AFT BEARING								
	PN-UNKNOWN	MOS			N:0			25-JUN-2016	
	SN-UNKNOWN	HRS/MSC	3000	+10%/-10%	N:0			3004:20	6004:20 6304:20
<b>DISCARD</b>	REF: AMM 24-30-04	AFL			N:0			2402	
+ 24-30/228 (s)	OPERATIONAL TEST EXTERNAL POWER						PKG		
	PKG 21	MOS	24	+10%/-10%				06-MAR-2020	
		HRS/MSC	2400	+10%/-10%				3576:24	
	REF: See Workcard	AFL						2920	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/482 (s)	BRUSH CHECK STARTER GENERATOR BRUSHES (P/N 978.91.23.407, 978.91.23.408 AND 978.91.23.409) <b>CMT ITEM</b> 978.91.23.408 PKG 18,19 P1079 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			PKG  24-MAR-2021 3708:16 3039		
+ 24-30/61	BRUSH CHECK STARTER GENERATOR BRUSHES (ALL P/N'S EXCEPT 978.91.23.407, 978.91.23.408 AND 978.91.23.409) <b>CMT ITEM</b> 978.91.23.408 P1079 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				28-MAY-2019 3363:06 2694		
+ 24-30/62	EXAMINE THE CORROSION PROTECTIVE LAYER GENERATOR 1 AND 2, BATTERY 1 AND 2 (IF INSTALLED) GROUND POINTS  REF: AMM 24-30-00	MOS HRS/MSC AFL	24	+10%/-10%		-4	10-FEB-2021 3700:03 3030	06-FEB-2023	18-APR-2023
+ 24-30/63	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES <b>CMT ITEM</b> 524.32.12.158 100505 REF: AMM 24-30-02	MOS HRS/MSC AFL	N/A						
+ 24-30/64 (s)	INSPECTION / CHECK GENERATOR 2 GENERATOR BRUSHES <b>CMT ITEM</b> 524.32.12.158 PKG 18 100505 REF: AMM 24-30-02	MOS HRS/MSC AFL	600	+10%/-10%			PKG  24-MAR-2021 3708:16 3039		
+ 24-30/65	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING  REF: AMM 24-30-04	MOS HRS/MSC AFL	N/A						





# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/66	INSPECT/CHECK GENERATOR # 2 DRIVE ASSEMBLY HOUSING	MOS					25-AUG-2016		
	REF: AMM 24-30-04	HRS/MSC AFL	1800	+10%/-10%			3004:02 2402	4804:02	4984:02
+ 24-30/67	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
	<b>CMT ITEM</b>								
24.060	976.17.31.302	MOS	12	+1m/-1m	-4		10-FEB-2021	06-FEB-2022	06-MAR-2022
	11400461	HRS/MSC	400	+10%/-10%			3700:03	4100:03	4140:03
	REF: AMM 24-30-07	AFL					3030		
+ 24-30/67	REMOVE AND SERVICE NO. 2 NICAD BATTERY								
	<b>CMT ITEM</b>								
24.060	976.17.31.302	MOS	12	+1m/-1m	-4		10-FEB-2021	06-FEB-2022	06-MAR-2022
	11400459	HRS/MSC	400	+10%/-10%			3700:03	4100:03	4140:03
	REF: AMM 24-30-07	AFL					3030		
+ 24-30/69	REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY								
	<b>CMT ITEM</b>								
24.010	PN	MOS							
	NOT INSTALLED	HRS/MSC	N/A						
	REF: AMM 24-30-07	AFL							
+ 24-30/69	REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY								
	<b>CMT ITEM</b>								
24.010	PN	MOS							
	NOT INSTALLED	HRS/MSC	N/A						
	REF: AMM 24-30-07	AFL							
+ 24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
		HRS/MSC	2400	+10%/-10%			3576:24		
	REF: GENERIC NO REF	AFL					2920		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-50/70	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY <b>CMT ITEM</b>								
24.050	985.83.14.953 3789 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	12	+1m/-1m		-4	10-FEB-2021 3700:03 3030	06-FEB-2022	06-MAR-2022
+ 24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 21	MOS HRS/MSC AFL	24	+10%/-10% +10%/-10%			06-MAR-2020 3576:24 2920		
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR 988.21.14.111 Y2267 <b>REF:</b> AMM 24-30-05	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-MAY-2003 0 0		
240025	NO. 2 GENERATOR CONTROL UNIT 988.21.15.102 10134 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-MAY-2003 0 0		
240035	BUSBAR,CROSS TIE RCCB 972.55.37.003 1045 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-MAY-2003 0 0		
240040	BUSBAR,CROSS,TIE RCCB 972.55.37.005 418 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-MAY-2003 0 0		
240045	STARTER RELAY 974.09.26.133 P324 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240050	BATTERY RELAY								
24.170	974.09.26.126 P661 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240055	EPU RELAY								
24.180	974.09.26.126 P468 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240057	GENERATOR 1 HIGH CURRENT RELAY								
	974.09.26.127 P403 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240059	GENERATOR 2 HIGH CURRENT RELAY								
	974.09.26.112 P776 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240060	CONTROL,EXTERNAL POWER UNIT								
24.110	972.81.32.301 352 REF: AMM 24-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240065	OVERHEAD PANEL								
24.190	972.81.32.102 JWPIL236 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240070	DUAL INVERTER								
	975.04.21.110 AGA00444 REF: AMM 24-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240073	VOLTAGE/CURRENT INDICATOR 959.90.20.124 193 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240090	S102 DC CURRENT SENSOR 974.29.00.201 2561 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240095	S105 DC CURRENT SENSOR 974.29.00.205 1739 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240100	S108 DC CURRENT SENSOR 974.29.00.205 1791 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240105	S103 DC CURRENT SENSOR 974.29.00.201 2684 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240110	S104 DC CURRENT SENSOR 974.29.00.201 2676 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
240115	S106 DC CURRENT SENSOR 974.29.00.201 2669 REF: AMM 24-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240135	NO. 1 LEAD ACID BATTERY								
24.010	PN NOT INSTALLED REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C						
240140	NO. 2 LEAD ACID BATTERY								
24.010	PN NOT INSTALLED REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C						
243045	GENERATOR 2								
24.030	524.32.12.158 100505 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	985.83.14.953 3789 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				06-FEB-2017 3075:06 2449		
243100	NO. 1 NICAD BATTERY								
24.060	976.17.31.302 11400461 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				10-FEB-2021 3700:03 3030		
243105	NO. 2 NICAD BATTERY								
24.060	976.17.31.302 11400459 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				10-FEB-2021 3700:03 3030		
24CUS01	REAR 2ND ELECTRICAL INSTRUMENT BATTERY								
	524.52.12.582 P813 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24CUS02	FUSELAGE 2ND ELECTRICAL INSTRUMENT BATTERY 524.52.12.586 P447 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
24CUS03	2ND WIRING HARNESS BATTERY 524.55.12.487 53937 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>									
+ 25-10/134 (s)	EXAMINE CREW SEAT BELTS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 25-10/294	CO-PILOT SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: AMM 25-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-FEB-2013		
+ 25-10/294	CREW SEAT BELTS PN-UNKNOWN SN-UNKNOWN REF: AMM 25-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-FEB-2013		
+ 25-10/294	PILOT SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: AMM 25-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-FEB-2013		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 10-FEB-2021 3700:03 3030		
+ 25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 15 ,16,17,18,19,20,21 REF: See Workcard	MOS HRS/MSC AFL	A/R				PKG 10-FEB-2021 3700:03 3030		
+ 25-10/300 (s)	REMOVE CREW SEAT CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
25-10/487	REPLACE BACKREST TUBES ON CREW SEATS WITHOUT RECLINE SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				23-MAY-2003 0 0	10000	
DISCARD									
+ 25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-20/295	NO. 1 PASSENGER SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-APR-2015 2790:20 2233		
+ 25-20/295	NO. 2 PASSENGER SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-APR-2015 2790:20 2233		
+ 25-20/295	NO. 3 PASSENGER SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-APR-2015 2790:20 2233		
+ 25-20/295	NO. 4 PASSENGER SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-APR-2015 2790:20 2233		
+ 25-20/295	NO. 5 PASSENGER SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-APR-2015 2790:20 2233		
+ 25-20/295	NO. 6 PASSENGER SEAT BELT PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-APR-2015 2790:20 2233		
+ 25-20/295 25.010	PASSENGER SEAT BELTS PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-APR-2015 2790:20 2233		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION PKG 15 ,16,17,18,19,20,21 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	A/R				PKG 10-FEB-2021 3700:03 3030		
+ 25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE THE INSPECTION PKG 15 ,16,17,18,19,20,21 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	A/R				PKG 10-FEB-2021 3700:03 3030		
+ 25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION. IF NECESSARY, REFER TO THE APPLICABLE SUPPLIER CMM (CMM 25-20-07 FOR EXECUTIVE SEATS AND CMM 25-20-99 FOR STANDARD SEATS). PKG 16 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 25-60/231 (s)	OPERATIONAL TEST ELT PKG 17 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 20 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
25-60/483	PERFORM PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED 985.13.80.853 L04950023 <b>REF:</b> AMM 25-63-10	MOS HRS/MSC AFL	N/A				23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-63/23	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY								
	S1820516-99	MOS		N:0			06-MAR-2020	01-AUG-2025 M	
25.020	TM0000167021	HRS/MSC	DUE	N:0			3576:24		
<b>DISCARD</b>	REF: GENERIC NO REF	AFL		N:0			2920		
Expiry Date: 01-AUG-2025									
25-CUS-01	INSPECT LIFE VEST								
		MOS	12	+10%/-10%			10-FEB-2021	10-FEB-2022	16-MAR-2022
		HRS/MSC					3700:03		
	REF:	AFL					3030		
25-CUS-02	EXPIRATION LIFE VESTS								
		MOS						09-OCT-2027 M	
		HRS/MSC	DUE						
	REF:	AFL							
250005	REMOTE CONTROL PANEL								
	985.13.80.852	MOS		N:0			23-MAY-2003		
25.070	M01150006	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
250010	EMERGENCY LOCATOR TRANSMITTER								
	985.13.80.853	MOS		N:0			23-MAY-2003		
25.050	L04950023	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-63-01	AFL		N:0			0		
250015	IPECO PILOT SEAT								
	959.30.01.133	MOS		N:0			23-MAY-2003		
25.040	808	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-10-05	AFL		N:0			0		
250020	IPECO CO-PILOT SEAT								
	959.30.01.134	MOS		N:0			23-MAY-2003		
25.040	815	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-10-05	AFL		N:0			0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250021	L/H NO. 1 AFSS PASSENGER SEAT 959.30.01.621 23018 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
250022	R/H NO. 2 AFSS PASSENGER SEAT 959.30.01.622 23019 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
250023	L/H NO. 3 FFSS PASSENGER SEAT 959.30.01.639 23020 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
250024	R/H NO. 4 FFSS PASSENGER SEAT 959.30.01.640 23022 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
250025	L/H NO. 5 FFSS PASSENGER SEAT 959.30.01.647 23021 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
250026	R/H NO. 6 FFSS PASSENGER SEAT 959.30.01.648 23023 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
250027	L/H NO. 7 STANDARD PASSENGER SEAT 959.30.01.639 23718 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-SEP-2003 117:36 122		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250028	R/H NO. 8 STANDARD PASSENGER SEAT 959.30.01.640 23719 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-SEP-2003 117:36 122		
+ 251010	PILOT SEAT BACKREST TUBES 959.30.01.131 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			21-MAY-2003 0 0	10000	
25.060 LIFE LIMIT									
+ 251015	COPILOT SEAT BACKREST TUBES 959.30.01.131 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			21-MAY-2003 0 0	10000	
LIFE LIMIT									
256030	ENTERTAINMENT SYSTEM 525.31.12.013 221109 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
+ 258010	PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION REF: See Workcard	MOS HRS/MSC AFL	N/A				20-FEB-2018 3195:20 2528		
25.085									
25C001	FIRST AID KIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
25C002	PERFORM FIRST AID KIT INSPECTION PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	12	+10%/-10%			10-FEB-2021 3700:03 3030	10-FEB-2022	16-MAR-2022

**CHAPTER 26 FIRE PROTECTION**

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20/2	CABIN FIRE EXTINGUISHER PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
+ 26-20/2	COCKPIT FIRE EXTINGUISHER BA51015GR-3 83927 REF: GENERIC NO REF LIFE LIMIT Manufacture Date: 01-NOV-2012	MOS HRS/MSC AFL	120	N:0 N:0 N:0			01-NOV-2012	01-NOV-2022	
+ 26-20/24	CONTENTS CHECK CABIN FIRE EXTINGUISHER PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
+ 26-20/24	CONTENTS CHECK COCKPIT FIRE EXTINGUISHER BA51015GR-3 83927 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+1m/-1m	24		10-FEB-2021 3700:03 3030	06-MAR-2022	06-APR-2022
26-20/515	CONTENTS CHECK CABIN FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224) PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-MAY-2003 0 0		
26-20/515	CONTENTS CHECK COCKPIT FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224) BA51015GR-3 83927 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-MAY-2003 0 0		
26-20/516	LIFE LIMIT CABIN FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224) PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-MAY-2003 0 0		
26-20/516	LIFE LIMIT COCKPIT FIRE EXTINGUISHER (MODEL P3APP003010D - P/N 959.08.06.224) BA51015GR-3 83927 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
260005	FIRE/OVERHEAT DETECTOR									
26.020	975.12.10.012 204757 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
<b>CHAPTER 27 FLIGHT CONTROLS</b>										
+ 27-00/138 (s)	OPERATE AILERON, ELEVATOR AND RUDDER CONTROLS MAKE SURE FULL AND FREE TRAVEL						PKG			
	PKG 16	MOS					10-FEB-2021			
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3700:03 3030			
+ 27-00/402	EXAMINE BONDING LEADS TO ALL FLIGHT CONTROL SURFACES									
		MOS					23-MAY-2003			
	REF: GENERIC NO REF	HRS/MSC AFL	32500 42000				0 0	32500 42000		
+ 27-00/71	EXAMINE FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES									
27.010		MOS	60	+10%/-10%	23		20-FEB-2018	15-MAR-2023	15-SEP-2023	
	REF: AMM 27-00-00	HRS/MSC AFL	4800	+10%/-10%			3195:20 2528	7995:20	8475:20	
+ 27-10/139 (s)	EXAMINE AILERON LH AND RH AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC TEMPORARY (MAT. NO. P10-001)						PKG			
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021			
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3700:03 3030			
+ 27-10/234 (s)	EXAMINE AILERON LH AND RH RODS AND LEVERS						PKG			
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021			
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030			
+ 27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG			
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021			
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030			

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/236 (s)	AILERON CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 27-10/237 (s)	CHECK AILERON CABLE TENSION MSN 101-683, MSN 684-999 PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 27-10/238 (s)	FUNCTIONAL TEST AILERONS MSN 101-683, MSN 684-999 PKG 21	MOS	24	+10%/-10%			PKG 06-MAR-2020		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			3576:24 2920		
+ 27-10/394	EXAMINE - AILERON CONTROL SYSTEM	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-10-00	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	
+ 27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-10-09	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	
+ 27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	
+ 27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	
+ 27-10/398	EDDY CURRENT INSPECTION AND MAGNETIC PARTICLE INSPECTIONS - AILERON BELLCRANKS	MOS							
<b>AIRWORTHINESS</b>	REF: See Workcard	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-60-06</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-60-06</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 27-10/444	AILERON FLIGHT CONTROL CABLES								
	527.10.12.113	MOS		N:0			23-MAY-2003		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	<b>20000</b>	
<b>LIFE LIMIT</b>	<b>REF: AMM 27-10-01</b>	AFL	27000	N:0			0	<b>27000</b>	
+ 27-10/445	AUTOPILOT CONTROL CABLE								
	527.10.12.144	MOS		N:0			23-MAY-2003		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	<b>20000</b>	
<b>LIFE LIMIT</b>	<b>REF: AMM 27-10-02</b>	AFL	27000	N:0			0	<b>27000</b>	
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARING						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	<b>REF: AMM 27-10-00</b>	AFL					3030		
+ 27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM MSN 101-683, MSN 684-999						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
		HRS/MSC	2400	+10%/-10%			3576:24		
	<b>REF: See Workcard</b>	AFL					2920		
+ 27-20/140 (s)	INSPECT/CHECK RUDDER						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	<b>REF: AMM 55-40-00</b>	AFL					3030		
+ 27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
		HRS/MSC	2400	+10%/-10%			3576:24		
	<b>REF: GENERIC NO REF</b>	AFL					2920		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/241 (s)	RUDDER CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 27-20/242 (s)	EXAMINE AILERON/RUDDER INTERCONNECT SYSTEM, MSN 101-683 MAKE SURE THE LOCKING MECHANISM IS FULLY ENGAGED WITH THE FLAPS AT 40° AND THE MOVING PARTS (PISTON AND HOUSING) ARE LUBRICATED. IF NECESSARY APPLY GREASE P04-002 WITH A BRUSH PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: AMM 20-31-00	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 21	MOS	24	+10%/-10%			PKG 06-MAR-2020		
	REF: See Workcard	HRS/MSC AFL	2400	+10%/-10%			3576:24 2920		
+ 27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 21	MOS	24	+10%/-10%			PKG 06-MAR-2020		
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%			3576:24 2920		
+ 27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 27-20/374	EXAMINE - RUDDER CONTROL SYSTEM	MOS							
	REF: AMM 27-20-00	HRS/MSC AFL	32500 42000					32500 42000	
<b>AIRWORTHINESS</b>									

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-20-04</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-20-05</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 27-20/431	CHECK L/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	A/R						
	<b>REF: AMM 27-20-00</b>	AFL							
+ 27-20/431	CHECK R/H RUDDER CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	A/R						
	<b>REF: AMM 27-20-00</b>	AFL							
+ 27-20/446	RUDDER FLIGHT CONTROL CABLES								
	527.20.10.098	MOS		N:0			23-MAY-2003		
<b>LIFE LIMIT</b>	<b>REF: AMM 27-20-01</b>	HRS/MSC	20000	N:0			0	<b>20000</b>	
		AFL	27000	N:0			0	<b>27000</b>	
+ 27-20/447	RUDDER AUTOPILOT CONTROL CABLES								
	527.20.12.105	MOS		N:0			23-MAY-2003		
<b>LIFE LIMIT</b>	<b>REF: AMM 27-20-02</b>	HRS/MSC	20000	N:0			0	<b>20000</b>	
		AFL	27000	N:0			0	<b>27000</b>	
+ 27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	<b>REF: GENERIC NO REF</b>	AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
+ 27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS PKG 21	MOS	24	+10%/-10%			PKG 06-MAR-2020 3576:24 2920		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%					
+ 27-30/249 (s)	ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
+ 27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%					
+ 27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 21	MOS	24	+10%/-10%			PKG 06-MAR-2020 3576:24 2920		
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%					
+ 27-30/334	CHECK ELEVATOR CONTROL CABLE TENSION AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND/OR ELEVATOR)	PN							
27.150	SN-UNKNOWN	MOS							
	REF: AMM 27-30-00	HRS/MSC AFL	A/R						
+ 27-30/363	EXAMINE - ELEVATOR CONTROL SYSTEM	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-30-00	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	
+ 27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-00-01	HRS/MSC AFL	32500 42000					32500 42000	
+ 27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 27-30-05	HRS/MSC AFL	32500 42000					32500 42000	
+ 27-30/448	ELEVATOR FLIGHT CONTROL CABLES	MOS							
<b>LIFE LIMIT</b>	527.30.12.044 SN-UNKNOWN REF: AMM 27-30-01	HRS/MSC AFL	20000 27000	N:0 N:0 N:0			23-MAY-2003 0 0	20000 27000	
+ 27-30/449	ELEVATOR AUTOPILOT CONTROL CABLES	MOS							
<b>LIFE LIMIT</b>	527.30.12.049 SN-UNKNOWN REF: AMM 27-30-02	HRS/MSC AFL	20000 27000	N:0 N:0 N:0			23-MAY-2003 0 0	20000 27000	
+ 27-30/450	STICK PUSHER CABLES	MOS							
<b>LIFE LIMIT</b>	527.30.12.066 SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	20000 27000	N:0 N:0 N:0			23-MAY-2003 0 0	20000 27000	
27-30/514 (s)	EXAMINE ELEVATOR STOPS	MOS	12	+10%/-10%			PKG		
	PKG 20	HRS/MSC	1200	+10%/-10%			10-FEB-2021 3700:03 3030		
	REF: AMM 55-20-01	AFL							
+ 27-40/1	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM RUNAWAY AURAL WARNING SYSTEM	MOS	12	+10%/-10%					
<b>AIRWORTHINESS</b>	27.021 REF: AMM 27-40-00	HRS/MSC AFL	3000		-4		10-FEB-2021 3700:03 3030	06-FEB-2022 6700:03	12-MAR-2022
+ 27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES	MOS	12	+10%/-10%			PKG		
	PKG 17	HRS/MSC	300	+10%/-10%			10-FEB-2021 3700:03 3030		
	REF: AMM 27-40-00	AFL							

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-40/25	PITCH TRIM ACTUATOR OVERHAUL								
27.020	978.73.14.203 434 REF: AMM 27-40-01	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			23-MAY-2003 0 0		
+ 27-40/252 (s)	INSPECTION/CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 20 REF: AMM 27-40-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			10-FEB-2021 3700:03 3030		
+ 27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
OVERHAUL	129-1-1100-02 1778 REF: AMM 27-40-01	MOS HRS/MSC AFL	84 3400				06-MAR-2020 3576:24 2920	06-MAR-2027 6976:24	
+ 27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 16 REF: AMM 27-40-00	MOS HRS/MSC AFL	300	+10%/-10%			10-FEB-2021 3700:03 3030		
+ 27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 20 REF: AMM 27-40-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			10-FEB-2021 3700:03 3030		
+ 27-40/3	PITCH TRIM ACTUATOR								
27.011	129-1-1100-02 1778 REF: AMM 27-40-01	MOS HRS/MSC AFL	20000 27000	O:0 O:0 O:0			06-MAR-2020 3576:24 2920	23576:24 29920	
27.036	REF: AMM 27-40-02	AFL							
27.036	REF: AMM 27-40-02	AFL							
+ 27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT (IPC 12-20-00-7) PARTS								
LIFE LIMIT	PN SN-UNKNOWN REF: AMM 27-40-02	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			21-MAY-2003 0 0	10000	
+ 27-50/143 (s)	LOWER FLAPS TO 40° AS NECESSARY TO DO INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				10-FEB-2021 3700:03 3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 17	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
+ 27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
+ 27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
+ 27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST. PRE SB 27-013, POST SB 27-013 AND MSN 401-999 <b>CMT ITEM</b> PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%					
+ 27-50/28	FLAP POWER DRIVE UNIT 978.73.20.003 0175	MOS			N:0		21-MAY-2003 0		
<b>OVERHAUL</b>	REF: See Workcard	HRS/MSC AFL	10000 13500		N:0 N:0		0 0	<b>10000</b> <b>13500</b>	
+ 27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.308 1214	MOS					21-MAY-2003 0		
27.040 <b>OVERHAUL</b>	REF: AMM 27-50-03	HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			0 0	<b>5000</b> <b>7000</b>	5500 7500
+ 27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.308 1223	MOS					21-MAY-2003 0		
27.040 <b>OVERHAUL</b>	REF: AMM 27-50-03	HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			0 0	<b>5000</b> <b>7000</b>	5500 7500
+ 27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED) 978.73.20.308 1209	MOS					21-MAY-2003 0		
27.050 <b>OVERHAUL</b>	REF: AMM 27-50-03	HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			0 0	<b>5000</b> <b>7000</b>	5500 7500

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.308	MOS					21-MAY-2003		
27.050	1212	HRS/MSC	5000	+10%/-10%			0	5000	5500
<b>OVERHAUL</b>	<b>REF: AMM 27-50-03</b>	AFL	7000	+500/-500			0	<b>7000</b>	7500
+ 27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	945.02.02.205	MOS					23-MAY-2003		
27.060	S5040	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: See Workcard</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	14000
+ 27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	945.02.02.206	MOS					23-MAY-2003		
27.060	S5092	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: See Workcard</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	14000
+ 27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	945.02.02.205	MOS					23-MAY-2003		
27.070	S5043	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: See Workcard</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	14000
+ 27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	945.02.02.206	MOS					23-MAY-2003		
27.070	S5080	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
<b>DISCARD</b>	<b>REF: See Workcard</b>	AFL	13500	+500/-500	N:0		0	<b>13500</b>	14000
+ 27-50/386	EXAMINE - FLAP MECHANISM								
		MOS							
		HRS/MSC	30000					30000	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	AFL	39000					<b>39000</b>	
+ 27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS							
		HRS/MSC	25000					25000	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	AFL	30000					<b>30000</b>	
+ 27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS							
		HRS/MSC	30000					30000	
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL	39000					<b>39000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FLTTINGS								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FLTTINGS								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 27-50/4	LEFT INBOARD FLAP ACTUATOR								
	978.73.20.308	MOS		N:0			23-MAY-2003		
27.040	1214	HRS/MSC	20000	N:0			0	<b>20000</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0	<b>27000</b>	
+ 27-50/4	LEFT OUTBOARD FLAP ACTUATOR								
	978.73.20.308	MOS		N:0			23-MAY-2003		
27.040	1223	HRS/MSC	20000	N:0			0	<b>20000</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0	<b>27000</b>	



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/4	RIGHT INBOARD FLAP ACTUATOR								
	978.73.20.308	MOS		N:0			23-MAY-2003		
27.050	1209	HRS/MSC	20000	N:0			0	20000	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0	27000	
+ 27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	978.73.20.308	MOS		N:0			23-MAY-2003		
27.050	1212	HRS/MSC	20000	N:0			0	20000	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-50-03</b>	AFL	27000	N:0			0	27000	
+ 27-50/414	LEFT HAND FLAP								
	557.50.12.003	MOS		N:0			23-MAY-2003		
57.060	410	HRS/MSC	25000	N:0			0	25000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	30000	N:0			0	30000	
+ 27-50/414	RIGHT HAND FLAP								
	557.50.12.004	MOS		N:0			23-MAY-2003		
57.060	408	HRS/MSC	25000	N:0			0	25000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	30000	N:0			0	30000	
+ 27-50/437	PERFORM IN-SITU INSPECTION/CHECK INBOARD FLAP DRIVE ARMS								
		MOS	12	+10%/-10%	24		10-FEB-2021	<b>06-MAR-2022</b>	12-APR-2022
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-00</b>	HRS/MSC	600	+10%/-10%			3700:03	<b>4300:03</b>	4360:03
		AFL					3030		
+ 27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	<b>REF: AMM 12-20-07</b>	AFL					3030		
+ 27-50/451	FLAP TENSION RODS								
	527.52.12.135	MOS		N:0			23-MAY-2003		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	AFL	27000	N:0			0	27000	
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS					10-FEB-2021		
		HRS/MSC	A/R				3700:03		
	<b>REF: GENERIC NO REF</b>	AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 945.02.02.205 S5040 REF: AMM 27-50-00	MOS HRS/MSC AFL	2000	+10%/-10%			20-JUN-2011 2086:59	4086:59	4286:59
+ 27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 945.02.02.206 S5092 REF: AMM 27-50-00	MOS HRS/MSC AFL	2000	+10%/-10%			20-JUN-2011 2086:59	4086:59	4286:59
+ 27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 945.02.02.205 S5043 REF: AMM 27-50-00	MOS HRS/MSC AFL	2000	+10%/-10%			20-JUN-2011 2086:59	4086:59	4286:59
+ 27-50/72	REMOVE/CLEAN/INSPECT/LUBRICATE RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT INNER CORE 945.02.02.206 S5080 REF: AMM 27-50-00	MOS HRS/MSC AFL	2000	+10%/-10%			20-JUN-2011 2086:59	4086:59	4286:59
+ 27-50/73	LUBRICATE LEFT INBOARD FLAP ACTUATOR (WHITE COLORED) 978.73.20.308 1214 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
+ 27-50/73	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (WHITE COLORED) 978.73.20.308 1223 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
+ 27-50/73	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (WHITE COLORED) 978.73.20.308 1209 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						
+ 27-50/73	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (WHITE COLORED) 978.73.20.308 1212 REF: AMM 27-50-00	MOS HRS/MSC AFL	N/A						

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/74 (s)	LUBRICATE LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)						PKG		
	978.73.20.308 PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
	1214	HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 27-50-00	AFL					3030		
+ 27-50/74 (s)	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)						PKG		
	978.73.20.308 PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
	1223	HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 27-50-00	AFL					3030		
+ 27-50/74 (s)	LUBRICATE RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)						PKG		
	978.73.20.308 PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
	1209	HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 27-50-00	AFL					3030		
+ 27-50/74 (s)	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)						PKG		
	978.73.20.308 PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
	1212	HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 27-50-00	AFL					3030		
+ 27-50/75	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (WHITE COLORED)								
27.040	978.73.20.308	MOS					20-FEB-2018		
	1214	HRS/MSC	N/A				3195:20		
	REF: AMM 27-50-03	AFL					2528		
+ 27-50/75	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (WHITE COLORED)								
27.040	978.73.20.308	MOS					20-FEB-2018		
	1223	HRS/MSC	N/A				3195:20		
	REF: AMM 27-50-03	AFL					2528		
+ 27-50/75	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (WHITE COLORED)								
27.050	978.73.20.308	MOS					20-FEB-2018		
	1209	HRS/MSC	N/A				3195:20		
	REF: AMM 27-50-03	AFL					2528		
+ 27-50/75	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (WHITE COLORED)								
27.050	978.73.20.308	MOS					20-FEB-2018		
	1212	HRS/MSC	N/A				3195:20		
	REF: AMM 27-50-03	AFL					2528		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.308	MOS	24	+10%/-10%			06-MAR-2020	06-FEB-2022	18-APR-2022
	1214	HRS/MSC	2400	+10%/-10%			3576:24	5976:24	6216:24
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			2920	6120	6440
+ 27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.308	MOS	24	+10%/-10%			06-MAR-2020	06-FEB-2022	18-APR-2022
	1223	HRS/MSC	2400	+10%/-10%			3576:24	5976:24	6216:24
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			2920	6120	6440
+ 27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.308	MOS	24	+10%/-10%			06-MAR-2020	20-FEB-2022	02-MAY-2022
	1209	HRS/MSC	2400	+10%/-10%			3576:24	5976:24	6216:24
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			2920	6120	6440
+ 27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								
	978.73.20.308	MOS	24	+10%/-10%			06-MAR-2020	06-FEB-2022	18-APR-2022
	1212	HRS/MSC	2400	+10%/-10%			3576:24	5976:24	6216:24
	REF: AMM 27-50-03	AFL	3200	+10%/-10%			2920	6120	6440
+ 27-50/77	PERFORM FLAP ELECTRICAL SYSTEM MAINTENANCE PRACTICES TESTS (MSN101 - 400 PRE SB27-013)								
27.080		MOS							
		HRS/MSC	N/A						
	REF: AMM 27-50-00	AFL							
270015	ELEVATOR LH ASSY								
	555.20.12.039	MOS					23-MAY-2003		
	411	HRS/MSC	O/C				0		
	REF: AMM 55-20-01	AFL					0		
270023	ELEVATOR RH ASSY								
	555.20.12.040	MOS					23-MAY-2003		
	411	HRS/MSC	O/C				0		
	REF: AMM 55-20-01	AFL					0		
270025	RUDDER TRIM LINEAR ACTUATOR								
	978.73.18.132	MOS					23-MAY-2003		
	552	HRS/MSC	O/C				0		
	REF: AMM 27-25-01	AFL					0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270033	RUDDER ASSY 555.40.12.038 414 REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270035	FLAP CONTROL AND WARNING (FCWU) UNIT 978.73.20.016 113203 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270045	LH INBOARD TRANSMITTER 978.73.20.021 018059DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270050	LH ROTATION TRANSMITTER 978.73.20.602 0284 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270060	LH OUTBOARD TRANSMITTER 978.73.20.021 018088DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270070	RH INBOARD TRANSMITTER 978.73.20.021 018052DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER 978.73.20.602 0278 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270090	AILERON TRIM LINEAR ACTUATOR 978.73.18.132 553 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270095	RH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 018087DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
270120	R/H RUDDER CONTROL CABLE								
	PN SN-UNKNOWN REF: AMM 27-20-01	MOS HRS/MSC AFL	O/C						
270121	L/H RUDDER CONTROL CABLE								
	PN SN-UNKNOWN REF: AMM 27-20-01	MOS HRS/MSC AFL	O/C						
270130	ELEVATOR CONTROL CABLE								
	PN SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C						
<b>CHAPTER 28 FUEL</b>									
+ 28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3700:03 3030		
+ 28-10/146 (s)	EXAMINE FUEL REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3700:03 3030		
+ 28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029		MOS					06-FEB-2017		
	REF: AMM 28-10-01	HRS/MSC AFL	2400	+10%/-10%			3075:06	5475:06	5715:06

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR PKG 17 REF: AMM 28-20-07	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT CMT ITEM PKG 17 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE OPERATE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (44.5 N) PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP CMT ITEM PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
+ 28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 06-MAR-2020 3576:24 2920		
+ 28-20/32	ENGINE DRIVEN FUEL PUMP 968.84.51.108 28.010 B5712 OVERHAUL REF: AMM 28-20-03	MOS HRS/MSC AFL	3500	+10%/-10%	O:0 N:3507 O:0 O:0	136:5 4	28-MAY-2019 3363:06 2694	7000	7350
+ 28-40/78	OPERATIONAL TEST FUEL LOW LEVEL WARNING SYSTEM 28.020 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+10%/-10% +10%/-10%		-38	06-MAR-2020 3576:24 2920	28-JAN-2024 4776:24	21-JUN-2024 4896:24

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280005	LOW PRESSURE FUEL PUMP								
28.120	968.84.51.108 B4432 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280010	FUEL FLOW TRANSMITTER								
28.130	TFF2905-50 00011 REF: AMM 73-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-APR-2021 3725:12 3069		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	963.87.22.301 1236 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	963.87.22.301 1233 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280025	FUEL FILTER ASSY								
28.025	968.35.21.001 00402 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	973.81.14.102 1006 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280035	LEFT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104 B2885 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280040	LEFT WING EJECTOR,DELIVERY PUMP								
28.030	968.84.71.105 B3225 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280045	FUEL QUANTITY OUTER SENSOR								
28.060	975.37.31.231 803 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280050	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 820 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280055	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 796 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280060	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 822 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280065	LEFT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.404 B5610A REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280070	RIGHT WING EJECTOR,TRANSFER PUMP								
28.040	968.84.71.104 B2891 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280075	RIGHT WING EJECTOR,DELIVERY PUMP								
28.030	968.84.71.105 B3006 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280080	FUEL QUANTITY,COLLECTOR SENSOR								
28.080	975.37.31.234 836 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280085	FUEL QUANTITY,INNER SENSOR								
28.090	975.37.31.233 805 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280090	FUEL QUANTITY,CENTRAL SENSOR								
28.070	975.37.31.232 822 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280095	FUEL QUANTITY,OUTER SENSOR								
28.060	975.37.31.231 827 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
280100	RIGHT WING FUEL,BOOSTER PUMP								
28.050	968.84.11.404 B5609A REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

CHAPTER	29	HYDRAULIC POWER
+	29-10/151 (s)	RETURN LINE FILTER DIIERENTIAL PRESSURE INDICATOR MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE
	PKG 19	MOS 12 +10%/-10% HRS/MSC 600 +10%/-10% REF: AMM 29-10-04 AFL
		10-FEB-2021 3700:03 3030
+	29-10/152 (s)	CHECK HYDRAULIC SYSTEM MSN 101-230 - CHECK FLUID SENSOR AND LEVEL USING MAINTENANCE SWITCH BOX. FILL AS NECESSARY MSN 231-999 - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NECESSARY
	PKG 17	MOS 12 +10%/-10% HRS/MSC 300 +10%/-10% REF: See Workcard AFL
		10-FEB-2021 3700:03 3030
+	29-10/153 (s)	CHECK RESERVOIR TANK MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY.
	PKG 17	MOS 12 +10%/-10% HRS/MSC 300 +10%/-10% REF: See Workcard AFL
		10-FEB-2021 3700:03 3030

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-10/257 (s)	EXAMINE POWER PACK ESPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291)						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: AMM 29-10-02	AFL					3030		
+ 29-10/259 (s)	REMOVE POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (POST SB 29-002 AND MSN 181-999) CLEAN AND RE-INSTALL						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 29-10/418	NITROGEN ACCUMULATOR								
	960.30.01.291	MOS			N:0		23-MAY-2003		
29.020	0414	HRS/MSC	25000		N:0		0	25000	
<b>LIFE LIMIT</b>	REF: AMM 29-10-02	AFL	30000		N:0		0	30000	
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)								
		MOS					23-MAY-2003		
		HRS/MSC	N/A				0		
	REF: AMM 29-10-02	AFL					0		
290005	LANDING GEAR STEER SELECTOR VALVE								
	960.30.01.271	MOS			N:0		23-MAY-2003		
29.040	0434AB	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
290015	PRESSURE GAGE SWITCH								
	973.81.14.304	MOS			N:0		23-MAY-2003		
29.050	0459T	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290025	SERVICE SELECTOR VALVE								
29.070	960.30.01.261 G0140609A REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
290030	PRESSURE GAUGE								
29.080	965.61.88.101 11214403 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
290035	(K 601) RELAY								
29.090	974.09.26.112 P693 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
290040	HAND PUMP								
29.030	529.21.12.021 413 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
290050	PRESSURE NITROGEN SWITCH								
29.100	973.81.14.306 468 REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
291010	HYDRAULIC POWER PACK								
29.010	960.30.01.154 G0310415 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
<b>CHAPTER 30</b>	<b>ICE AND RAIN PROTECTION</b>								
+ 30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 30-10-00	AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM MSN 101-320 AND 322-400. MSN 321 AND 401-999 PKG 19	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: See Workcard	HRS/MSC	600	+10%/-10%			3700:03		
		AFL					3030		
+ 30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 20	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: AMM 30-10-00	HRS/MSC	1200	+10%/-10%			3700:03		
		AFL					3030		
+ 30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1	MOS	6	+10%/-10%			10-FEB-2021	10-AUG-2021	28-AUG-2021
30.010	REF: GENERIC NO REF	HRS/MSC					3700:03		
		AFL					3030		
+ 30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS CMT ITEM PKG 17	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			3700:03		
		AFL					3030		
+ 30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 20	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			3700:03		
		AFL					3030		
+ 30-30/157 (s)	OPERATIONAL TEST PROBES DE-ICE SYSTEM PKG 19	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: See Workcard	HRS/MSC	600	+10%/-10%			3700:03		
		AFL					3030		
+ 30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 21	MOS	24	+10%/-10%			PKG	06-MAR-2020	
	REF: See Workcard	HRS/MSC	2400	+10%/-10%			3576:24		
		AFL					2920		
+ 30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 19	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: AMM 30-60-00	HRS/MSC	600	+10%/-10%			3700:03		
		AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 19 REF: See Workcard	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
30-CUS-01	GA35 ANTENNA 013-00235-00 158173 REF:	MOS HRS/MSC AFL	O/C				28-MAY-2019 3363:06 2694		
300005 30.140	PROP DE-ICE TIMER/ CONTROLLER 968.29.13.227 U0325 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300010 30.150	LPMI LINEAR ACTUATOR 978.73.15.301 28515 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300015 30.160	REGULATOR-RELIEVER ASSY 9598901012 N0500 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			31-DEC-2019 3550:21 2896		
300020 30.110	L132 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008 N2140 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300025 30.120	L133 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 959.89.01.008 N2141 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300030 30.110	L131 EMPENAGE EJECTOR FLOW CONTROL VALVE 959.89.01.008 N2123 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300035	L134 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	959.89.01.008 N2064 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300040	L135 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	959.89.01.008 N2121 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	973.81.14.312 1966 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300050	WATER SEPARATOR								
30.060	959.89.01.010 B1300 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300055	AEROFOIL DE-ICING SYSTEM TIMER								
30.100	959.89.01.014 U0432 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 113361 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 113372 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300070	S133 LOWER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 1823 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300075	S134 UPPER SURF INBD WING PRESSURE GAGE SWITCH								
30.080	973.81.14.312 1824 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300080	S135 LOWER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 1888 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300085	S136 UPPER SURF OUTBD WING PRESSURE GAGE SWITCH								
30.090	973.81.14.312 1884 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.035 MX97JR0 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.036 MX93O20 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300100	RH INBD-WING DE-ICER BOOT								
30.040	P27-7D5221-22 NFB8100 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-OCT-2019 3527 2870		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.034 MX9PYL0 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
300115	LH INBD-WING DE-ICER BOOT								
30.040	959.89.01.031 MX90GQ0 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.033 MX9G8T0 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
<b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b>									
+ 31-50/34	CAWS & CACU CLOCK BATTERY								
31.010	PN SN-UNKNOWN REF: AMM 31-50-03	MOS HRS/MSC AFL	24	+10%/-10%		50	10-FEB-2021 3700:03 3030	01-APR-2023	13-JUN-2023
DISCARD									
310020	FLAP POSITION INDICATOR								
31.090	975.44.16.203 00377 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
310035	CAWS COMPUTER								
31.050	972.81.32.031 084 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
310050	DIGITAL CLOCK								
31.040	999.61.11.212 1015794 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
<b>CHAPTER 32 LANDING GEAR</b>									
+ 32-10/162 (s)	LUBRICATE MAIN LANDING GEAR							PKG	
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021		
	REF: AMM 12-20-04	HRS/MSC AFL	600	+10%/-10%			3700:03 3030		
+ 32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS							PKG	
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			3700:03 3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 19	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
+ 32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 19	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: AMM 32-10-00	HRS/MSC AFL	600	+10%/-10%					
+ 32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%					
+ 32-10/264	REMOVE MAIN LANDING GEAR LEFT AND RIGHT AXLE BOLT (PRE SB 32-006) AND EXAMINE. REPLACE IF DAMAGED. INSTALL A SERVICEABLE BOLT.	MOS					20-FEB-2018 3195:20 2528		
	REF: GENERIC NO REF	HRS/MSC AFL	N/A						
+ 32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG YOKE FITTING	MOS							
<b>AIRWORTHINESS</b>	REF:	HRS/MSC AFL	25000 30000					<b>25000</b> <b>30000</b>	
+ 32-10/346	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG YOKE FITTING	MOS							
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000					<b>25000</b> <b>30000</b>	
+ 32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF LEFT MLG TRAILING LINK	MOS							
<b>AIRWORTHINESS</b>	REF:	HRS/MSC AFL	25000 30000					<b>25000</b> <b>30000</b>	
+ 32-10/347	OVERHAUL AND EDDY CURRENT INSPECTION OF RIGHT MLG TRAILING LINK	MOS							
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC AFL	25000 30000					<b>25000</b> <b>30000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/436	EXAMINE MAIN LANDING GEAR SHOCK ABSORBER TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS.  REF: AMM 32-10-00	MOS HRS/MSC AFL	12	+10%/-10%			10-FEB-2021 3700:03 3030	<b>10-FEB-2022</b>	16-MAR-2022
+ 32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT  REF: AMM 32-10-00	MOS HRS/MSC AFL	72				28-JAN-2016 2895:15	<b>28-JAN-2022</b>	
+ 32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT  REF: AMM 32-10-00	MOS HRS/MSC AFL	72				28-JAN-2016 2895:15	<b>28-JAN-2022</b>	
+ 32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS 10-1537 0929 REF: AMM 12-20-06	MOS HRS/MSC AFL	12	+1m/-1m T/C	-4		10-FEB-2021 3700:03 3030	<b>06-FEB-2022</b>	06-MAR-2022
+ 32-10/80	LUBRICATE NOSE WHEEL BEARINGS 959.56.02.301 0477 REF: AMM 12-20-06	MOS HRS/MSC AFL	12	+1m/-1m T/C	-4		10-FEB-2021 3700:03 3030	<b>06-FEB-2022</b>	06-MAR-2022
+ 32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS 3-1543-1 1991 REF: AMM 12-20-06	MOS HRS/MSC AFL	12	+1m/-1m T/C	-4		10-FEB-2021 3700:03 3030	<b>06-FEB-2022</b>	06-MAR-2022
+ 32-10/81  32.010	INSPECTION/CHECK MAIN LANDING GEAR HINGE PIN AND BUSHES  REF: AMM 32-10-00	MOS HRS/MSC AFL	12 2400	+1m/-1m +10%/-10%	-4		10-FEB-2021 3700:03 3030	<b>06-FEB-2022</b> <b>6100:03</b>	06-MAR-2022 6340:03

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE PKG 19	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: AMM 32-20-00	HRS/MSC	600	+10%/-10%			3700:03		
		AFL					3030		
+ 32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 19	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: AMM 12-20-04	HRS/MSC	600	+10%/-10%			3700:03		
		AFL					3030		
+ 32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.134) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 19	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			3700:03		
		AFL					3030		
+ 32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 19	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			3700:03		
		AFL					3030		
+ 32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 20	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			3700:03		
		AFL					3030		
+ 32-20/266	REMOVE NOSE LANDING GEAR SPRING STRUT PART NO. 532.20.12.250 CLEAN AND LUBRICATE	MOS						20-FEB-2018	
	REF: See Workcard	HRS/MSC	N/A					3195:20	
		AFL						2528	
+ 32-20/305 (s)	EXAMINE NOSE LANDING GEAR ACTUATOR FUSELAGE ATTACHMENT FITTING (PART NO. 553.10.12.326) IF CRACKS ARE FOUND REPLACE ATTACHMENT FITTING PKG 20	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF:	HRS/MSC	1200	+10%/-10%			3700:03		
		AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20/335	NOSE LANDING GEAR TORQUE TUBE								
32.175	532.50.12.064 SN-UNKNOWN REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C						
+ 32-20/336	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT DRAG LINK								
32.180	REF: AMM 32-20-06	MOS HRS/MSC AFL	N/A				20-JUN-2012 2272:15 1844		
+ 32-20/403	NOSE LANDING GEAR								
<b>OVERHAUL</b>	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	25000 30000					25000 30000	
+ 32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
<b>LIFE LIMIT</b>	532.20.12.296 SN-UNKNOWN REF: AMM 32-20-05	MOS HRS/MSC AFL	25000 30000	N:0 N:0 N:0			20-JUN-2012 2272:15 1844	27272:15 31844	
+ 32-20/5	NOSE LANDING GEAR UPPER RIGHT DRAG LINK								
32.020	532.20.12.296 SN-UNKNOWN REF: AMM 32-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUN-2012 2272:15 1844		
+ 32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM								
	<b>CMT ITEM</b>								
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
	REF: AMM 32-30-00	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 32-30/417	LEFT HAND MAIN LANDING GEAR ACTUATOR								
32.040	960.30.01.103 0877E	MOS HRS/MSC	25000				23-MAY-2003 0	25000	
<b>LIFE LIMIT</b>	REF: AMM 32-30-01	AFL	30000	N:0			0	30000	
+ 32-30/417	RIGHT HAND MAIN LANDING GEAR ACTUATOR								
32.040	960.30.01.103 0875E	MOS HRS/MSC	25000				23-MAY-2003 0	25000	
<b>LIFE LIMIT</b>	REF: AMM 32-30-01	AFL	30000	N:0			0	30000	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				28-JAN-2016 2895:15	28-JAN-2022	
	REF: AMM 32-10-00	HRS/MSC AFL							
+ 32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				28-JAN-2016 2895:15	28-JAN-2022	
	REF: AMM 32-10-00	HRS/MSC AFL							
32-30/518	LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE	MOS							
	REF: GENERIC NO REF	HRS/MSC AFL	N/A						
32-30/518	RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE	MOS					10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	N/A						
+ 32-40/171 (s)	EXAMINE MAINWHEELS ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					
+ 32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021 3700:03 3030		
	REF: AMM 12-10-04	HRS/MSC AFL	300	+10%/-10%					
+ 32-40/173 (s)	EXAMINE NOSEWHEEL ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%					

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE PKG 17	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: AMM 12-10-04	HRS/MSC AFL	300	+10%/-10%					
+ 32-40/175 (s)	EXAMINE BRAKE SYSTEM APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING. PKG 17	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%					
+ 32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY PKG 17	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: AMM 12-10-02	HRS/MSC AFL	300	+10%/-10%					
+ 32-50/404	EXAMINE NOSE LANDING GEAR STEERING MECHANISM	MOS					23-MAY-2003 0 0	32500 42000	
	REF: AMM 32-50-00	HRS/MSC AFL	32500 42000						
320005	PILOT LH BRAKE MASTER CYLINDER 959.47.51.131	MOS			N:0		23-MAY-2003 0 0		
32.130	3455	HRS/MSC AFL	O/C		N:0 N:0				
	REF: AMM 32-40-04	AFL			N:0				
320010	PILOT RH BRAKE MASTER CYLINDER 959.47.51.131	MOS			N:0		23-MAY-2003 0 0		
32.130	3470	HRS/MSC AFL	O/C		N:0 N:0				
	REF: AMM 32-40-04	AFL			N:0				
320015	PARK BRAKE VALVE 959.47.51.121	MOS			N:0		23-MAY-2003 0 0		
32.140	2125	HRS/MSC AFL	O/C		N:0 N:0				
	REF: AMM 32-40-05	AFL			N:0				
320020	NOSE WHEEL 959.56.02.301	MOS			N:0		23-MAY-2003 0 0		
32.150	0477	HRS/MSC AFL	O/C		N:0 N:0				
	REF: AMM 32-40-02	AFL			N:0				

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320021	NOSE LANDING GEAR TIRE 9595602311 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-FEB-2018 3195:20 2528		
320022	LEFT MAIN LANDING GEAR WHEEL 10-1537 0929 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				28-MAY-2019 3363:06 2694		
320023	LEFT MAIN LANDING GEAR TIRE 025-350-0 8087500318 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-MAY-2019 3363:06 2694		
320024	RIGHT MAIN LANDING GEAR WHEEL 3-1543-1 1991 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				28-MAY-2019 3363:06 2694		
320025	SHIMMY DAMPER ASSY 532.20.12.215 IL-318 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320026	RIGHT MAIN LANDING GEAR TIRE 025-350-0 8057500301 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-MAY-2019 3363:06 2694		
320030	COPILOT LH BRAKE MASTER CYLINDER 959.47.51.131 3478 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320035	COPILOT RH BRAKE MASTER CYLINDER 959.47.51.131 3483 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	532.20.12.249 IL-312 REF: AMM 32-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	532.20.12.038 IL-312 REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			24-MAR-2021 3708:16 3039		
320050	LEFT SHOCK ABSORBER ASSY								
32.060	532.10.12.175 IL-673 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	532.10.12.175 IL-676 REF: AMM 32-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320065	LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	532.10.12.049 IL-337 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320070	RIGHT MAIN LANDING GEAR ASSEMBLY								
32.070	532.10.12.050 IL-337 REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320074	NOSE LANDING GEAR ACTUATOR								
29.060	960.30.01.111 0436A REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320075	LH BRAKE ASSY								
32.050	959.56.01.512 0093 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320080	RH BRAKE ASSY								
32.050	959.56.01.512 0089 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320090	LH WHEEL & COVER ASSY								
32.110	959.56.01.501 0917 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
320095	RH WHEEL & COVER ASSY								
32.110	959.56.01.501 0929 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

CHAPTER 33 LIGHTS									
+ 33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING							PKG	
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: See Workcard	AFL					3030		
+ 33-41/178 (s)	EXAMINE LANDING LIGHTS							PKG	
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 33-41-01	AFL					3030		
+ 33-42/179 (s)	EXAMINE TAXI LIGHTS							PKG	
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 33-42-01	AFL					3030		
+ 33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS							PKG	
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 17	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%				3700:03 3030	
+ 33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 17	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%				3700:03 3030	
330005	DIM UNIT 975.02.15.205 112728	MOS						23-MAY-2003	
33.080	REF: AMM 33-10-04	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
330010	DE-ICE LIGHT ASSY 972.87.67.111 355379	MOS						23-MAY-2003	
33.010	REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
330015	LEFT WING POWER SUPPLY, HIDL UNIT 972.87.69.413 344442	MOS						23-MAY-2003	
33.020	REF: AMM 33-40-11	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
330020	RIGHT WING POWER SUPPLY, HIDL UNIT 972.87.69.413 344422	MOS						23-MAY-2003	
33.020	REF: AMM 33-40-11	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY 972.87.87.331 13674	MOS						23-MAY-2003	
33.040	REF: AMM 33-46-01	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY 972.87.87.332 13709	MOS						23-MAY-2003	
33.040	REF: AMM 33-46-01	HRS/MSC AFL	O/C		N:0 N:0 N:0			0 0 0	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330035	LH WING POWER SUPPLY UNIT								
33.070	972.87.87.164 19695 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
330040	LEFT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 19603 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
330045	RH WING POWER SUPPLY UNIT								
33.070	972.87.87.164 18894 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
330050	RIGHT WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 19596 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

CHAPTER	NAVIGATION								
+ 34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
		HRS/MSC	2400	+10%/-10%			3576:24		
	REF: GENERIC NO REF	AFL					2920		
+ 34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 34-11/185 (s)	EXAMINE PITOT TUBE						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11/186 (s)	EXAMINE STATIC PORTS PKG 17	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3700:03 3030		
+ 34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM SINGLE SYSTEM, DUAL SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 34-11/82	LEAK CHECK STATIC SYSTEM	MOS	24		-37		06-MAR-2020	28-JAN-2022	
34.010	REF: See Workcard	HRS/MSC AFL					3576:24 2920		
+ 34-14/83	CALIBRATION CHECK ALTIMETER	MOS	24		-37		06-MAR-2020	28-JAN-2022	
34.020	REF: See Workcard	HRS/MSC AFL					3576:24 2920		
+ 34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS	MOS	24	+10%/-10%	-37		06-MAR-2020	28-JAN-2022	09-APR-2022
34.030	REF: AMM 34-21-00	HRS/MSC AFL					3576:24 2920		
+ 34-25/85	CHECK SWING ATTITUDE HEADING REFERENCE SYSTEM (AHRS)	MOS	24	+10%/-10%	-37		06-MAR-2020	28-JAN-2022	09-APR-2022
34.040	REF: AMM 34-25-00	HRS/MSC AFL					3576:24 2920		
+ 34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)	MOS	24		-37		06-MAR-2020	28-JAN-2022	
34.050	REF: See Workcard	HRS/MSC AFL					3576:24 2920		
34-CUS-02	GARMIN GTN650 GPS/NAV/COM1 010-00813-50 1Z8026365	MOS					28-MAY-2019		
	REF:	HRS/MSC AFL	O/C				3363:06 2694		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340005	PILOT ALTIMETER PN 03100201BA REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C					20-FEB-2018 3195:20 2528	
340006	COPILOT ALTIMETER PN 03010125BD REF: AMM 34-14-12	MOS HRS/MSC AFL	O/C					20-FEB-2018 3195:20 2528	
340007	NO. 1 TRANSPONDER 011-00455-70 84206563 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C					28-MAY-2019 3363:06 2694	
340009	NO. 1 DME/IFF ANTENNA 984.81.10.240 60671 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAY-2003 0 0	
340010	PILOT VERTICAL SPEED INDICATOR 965.16.15.101 303225 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAY-2003 0 0	
340014	MARKER,KR21 RECEIVER 985.99.11.001 23165 REF: AMM 34-32-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAY-2003 0 0	
340015	PILOT ATTITUDE INDICATOR 975.96.11.241 25444 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAY-2003 0 0	
340020	MARKER ANTENNA 984.81.10.260 5468 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAY-2003 0 0	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340025	EFIS 1 SG465 SYMBOL GENERATOR								
34.300	975.96.32.402 3139 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340026	STAND-BY ALTIMETER								
31.020	965.23.22.101 423811 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340030	COPILOT VERTICAL SPEED INDICATOR								
31.070	965.16.15.101 301925 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340034	EFIS 1 CONTROL,CP467 PANEL								
34.230	975.96.32.441 3214 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340035	PILOT UPPER EADI/EHSI ED551A DISPLAY								
34.170	975.96.32.423 4362 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340040	PILOT LOWER EADI/EHSI ED551A DISPLAY								
34.170	975.96.32.423 4360 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340044	TRIM TRIPLE INDICATOR								
31.100	975.44.16.204 00407 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340045	CO-PILOT UPPER EADI/EHSI DISPLAY								
34.180	975.96.32.423 4368 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340050	CO-PILOT LOWER EADI/EHSI DISPLAY								
34.180	975.96.32.423 4262 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340055	PILOT AIRSPEED INDICATOR								
31.110	965.12.13.334 1020406 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340059	WITH HARM FILTER,KN63 DME								
34.200	985.99.11.101 27600 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340060	COPILOT AIRSPEED INDICATOR								
31.110	965.12.13.335 1020409 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340065	WX-RADAR RT UNIT								
34.360	071-01519-0101 9573 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			22-MAY-2018 3269:48 2609		
340070	RADAR CONTROL PANEL								
34.240	985.99.11.518 2378 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340075	WX,VERTICAL ANTENNA								
34.370	985.99.11.504 3268 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340080	NO. 2 TRANSPONDER								
34.080	011-00455-70 84206571 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-MAY-2019 3363:06 2694		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340085	ADF,KA44B ANTENNA								
34.070	985.99.11.167 78919 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340095	VHF/NAV SYSTEM II NAV,DUAL,KN40 CONVERTER								
34.150	975.96.32.482 12308 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340100	FRONT KA92 GPS ANTENNA								
34.090	985.99.11.193 47105 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340101	REAR KA92 GPS ANTENNA								
34.090	985.99.11.193 46915 REF: AMM 34-57-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340105	LH NAV/GS ANTENNA								
34.380	984.81.10.280 4648 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340110	NO. 1 CAL PROM AHRS,LCR-92 UNIT								
34.390	985.99.11.823 3104 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340111	AHRS NO 1 LCR-92,WSYNCHR,124210-2022 AHRU								
34.060	985.99.11.878 1045 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340115	VR/LC/GS/CV,KI204 INDICATOR								
34.220	985.99.11.302 55658 REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340120	PILOT SIDE RMI,KNI582-1 INDICATOR								
34.210	066-3060-01 10116 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C				10-FEB-2021 3700:03 3030		
340125	COPILLOT SIDE RMI,KNI582-1 INDICATOR								
34.210	985.99.11.771 10682 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340130	AIR DATA COMPUTER								
34.400	985.92.03.111 2284 REF: AMM 34-13-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	985.99.11.865 11166 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340135	MAGNETIC,STANDBY COMPASS								
34.130	999.98.80.103 AT-453 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340140	4206-100-V2 RADOME								
34.420	985.79.00.003 410 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340145	ANTENNA,VHF NAV COUPLER								
34.160	984.81.10.412 3324 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340150	EFIS 2 SG465 SYMBOL GENERATOR								
34.300	975.96.32.402 5142 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 25883 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 25537 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 7864 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 8146 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340165	DATA BASE,ATLANTIC,KLN90 UNIT								
34.440	985.99.11.224 28651 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	985.99.11.570 3618 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340175	EFIS 2 CONTROL,CP467 PANEL								
34.230	975.96.32.441 3220 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340180	NO. 2 CAL PROM AHRS,LCR-92 UNIT								
34.390	985.99.11.823 3540 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340185	KA138 RELAY								
34.450	985.99.11.350 5309 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340190	ADF,W/SUPERFLAG,KR87SC+ RECEIVER								
34.280	066-1072-14 71201 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			31-DEC-2019 3550:21 2896		
340195	MULTI FUNCTION DISPLAY								
34.190	985.99.11.863 4521 REF: AMM 34-26-30	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340200	PCB MODULE,KAC501 WX RADAR UNIT								
34.460	985.90.03.045 3001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340205	PCB MODULE,KAC502 EGPWS UNIT								
34.470	985.90.03.044 2657 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340210	PCB MODULE,KAC504 TCAS UNIT								
34.480	985.90.03.046 2611 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340215	AHRS NO2 AHRU,LCR-92,WSYNCHR,124210-2022 UNIT								
34.320	985.99.11.878 1044 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340220	STORMSCOPE WX-500 PROCESSOR								
34.270	985.99.18.006 83196 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340223	KMH820 TAWS/TAS PROCESSOR								
34.260	985.99.11.872 1627 REF: AMM 34-45-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340225	STORMSCOPE WX-500 ANTENNA								
34.120	985.99.18.009 83268 REF: AMM 34-41-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340230	RH NAV/GS ANTENNA								
34.380	984.81.10.280 4649 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340235	AOA SENSOR RH UNIT								
34.330	975.44.21.422 0485 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340240	NO. 1 FLUX,KMT112 VALVE								
34.350	985.99.11.064 66560 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	985.99.11.505 10288 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340250	OUTSIDE AIR TEMPERATURE PROBE								
34.250	975.11.20.111 1162 REF: AMM 34-13-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
340255	AOA SENSOR LH UNIT								
34.330	975.44.21.421 0465 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
340260	NO. 2 FLUX,KMT112 VALVE									
34.350	985.99.11.064 66573 REF: AMM 34-25-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
341005	LH AOA PLATE TEMP CONTROLLER									
30.170	975.44.21.417 U0962 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
341010	RH AOA PLATE TEMP CONTROLLER									
30.170	975.44.21.417 U0959 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
34CUS02	AIR DATA COMPUTER									
	04471-02-03-03 20086-363 REF:	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			21-SEP-2018 3342:46 2677			
34CUS03	DC-DC POWER CONVERTER									
	975.02.15.106 936 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
<b>CHAPTER 35 OXYGEN</b>										
+ 35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) MAKE SURE THAT IT IS NOT DAMAGED						PKG			
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021			
		HRS/MSC	300	+10%/-10%			3700:03			
	REF: GENERIC NO REF	AFL					3030			
+ 35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS						PKG			
	PKG 16	MOS					10-FEB-2021			
		HRS/MSC	300	+10%/-10%			3700:03			
	REF: GENERIC NO REF	AFL					3030			

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 35-10/270 (s)	OPERATIONAL TEST OXYGEN SYSTEM PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021		
	REF: AMM 35-00-00	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 35-10/6	OXYGEN BOTTLE <b>CMT ITEM</b> 895-06077	MOS	180	O:0			28-MAY-2019	<b>01-AUG-2030</b>	
35.010	C15100477	HRS/MSC		O:0			3363:06		
<b>AIRWORTHINESS</b>	REF: AMM 35-10-01	AFL		O:0			2694		
	Manufacture Date: 01-AUG-2015								
+ 35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE <b>CMT ITEM</b> 895-06077	MOS	60				01-JAN-2019	<b>01-JAN-2024</b>	
35.010	C15100477	HRS/MSC							
	REF: GENERIC NO REF	AFL							
+ 35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS	MOS	36	+10%/-10%		78	10-FEB-2021	<b>28-APR-2024</b>	15-AUG-2024
35.010	REF: AMM 35-20-00	HRS/MSC AFL					3700:03 3030		
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY 957.12.01.206	MOS		N:0			23-MAY-2003		
35.040	105582	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY MC10-06-125	MOS		N:0			15-OCT-2020		
35.040	B162170	HRS/MSC	O/C	N:0			3683:55		
	REF: GENERIC NO REF	AFL		N:0			3016		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
350030	PRESSURE,GAGE,OXYGEN SWITCH									
35.050	973.81.14.401 352 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
350035	3-POSITION CONTROL VALVE									
35.030	963.32.11.101 1652 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
350040	ALTITUDE SENSING SWITCH									
35.020	973.81.52.102 543 REF: AMM 35-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
350045	OXYGEN GAGE ASSY									
	535.12.12.085 00069 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
35CUS01	OXYGEN PRESSURE TRANSDUCER									
	957.12.01.184 6056-4-248 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
<b>CHAPTER 52 DOORS</b>										
+ 52-10/189 (s)	CLEAN PASSENGER/CREW DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG			
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021			
		HRS/MSC	600	+10%/-10%			3700:03			
	REF: GENERIC NO REF	AFL					3030			
+ 52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG			
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021			
		HRS/MSC	600	+10%/-10%			3700:03			
	REF: GENERIC NO REF	AFL					3030			



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10/191 (s)	MAKE SURE PASSENGER/CREW DOOR HANDLE LOCK PIN MOVEMENT IS FREE						PKG		
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	600	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	600	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
		MOS							
		HRS/MSC	32500						32500
<b>AIRWORTHINESS</b>	REF: AMM 52-10-00	AFL	42000						42000
+ 52-10/405	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR PIANO HINGE								
		MOS					23-MAY-2003		
		HRS/MSC	32500				0		32500
	REF: AMM 52-00-01	AFL	42000				0		42000
+ 52-10/406	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SKIN								
		MOS					23-MAY-2003		
		HRS/MSC	25000				0		25000
	REF: AMM 52-10-01	AFL	30000				0		30000
52-10/472	EDDY CURRENT INSPECTION PASSENGER/CREW DOOR SHOOT BOLT FITTING ONLY IF SB 52-007 PART C IS DONE								
		MOS					23-MAY-2003		
		HRS/MSC	N/A				0		
	REF: AMM 52-10-06	AFL					0		
+ 52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
		MOS	48	+10%/-10%		-30	28-MAY-2019	28-APR-2023	21-SEP-2023
52.010		HRS/MSC	4000	+10%/-10%			3363:06	7363:06	7763:06
	REF: See Workcard	AFL					2694		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED) PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 52-20/273 (s)	CLEAN EMERGENCY DOOR SEAL WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 52-20-00	HRS/MSC AFL	32500 42000					<b>32500</b> <b>42000</b>	
+ 52-30/193 (s)	CLEAN CARGO DOOR SEAL WITH A DRY CLOTH, EXAMINE AND APPLY P09-002 FRENCH CHALK PKG 19	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			3700:03 3030		
+ 52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS PKG 19	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: AMM 52-30-00	HRS/MSC AFL	600	+10%/-10%			3700:03 3030		
+ 52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT PKG 19	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			3700:03 3030		
+ 52-30/274 (s)	EXAMINE CARGO DOOR PKG 20	MOS	12	+10%/-10%			PKG 10-FEB-2021 3700:03 3030		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 52-30-00</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 52-30/407	EDDY CURRENT INSPECTION CARGO DOOR PIANO HINGE	MOS					23-MAY-2003		
		HRS/MSC	32500				0	<b>32500</b>	
	<b>REF: AMM 52-30-00</b>	AFL	42000				0	<b>42000</b>	
+ 52-30/408	EDDY CURRENT INSPECTION CARGO DOOR SKIN	MOS					23-MAY-2003		
		HRS/MSC	25000				0	<b>25000</b>	
	<b>REF: AMM 52-30-01</b>	AFL	30000				0	<b>30000</b>	
+ 52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS	MOS					21-MAY-2003		
52.020	PN	HRS/MSC	13000	N:0			0	<b>13000</b>	
<b>AIRWORTHINESS</b>	<b>REF: AMM 52-30-07</b>	AFL	17000	N:0			0	<b>17000</b>	
+ 52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM	MOS	48	+10%/-10%			28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
52.030		HRS/MSC	4000	+10%/-10%	-30		3363:06	<b>7363:06</b>	7763:06
	<b>REF: See Workcard</b>	AFL					2694		
+ 52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM	MOS	12	+10%/-10%			10-FEB-2021		
	PKG 20	HRS/MSC	1200	+10%/-10%			3700:03		
	<b>REF: AMM 52-70-00</b>	AFL					3030		
520005	PASSENGER DOOR	MOS					23-MAY-2003		
52.050	552.05.12.007	HRS/MSC	O/C	N:0			0		
	403	AFL		N:0			0		
	<b>REF: AMM 52-10-01</b>			N:0			0		
520010	FREIGHT OF 10SERIE DOOR ASSY	MOS					23-MAY-2003		
52.040	552.05.12.010	HRS/MSC	O/C	N:0			0		
	401	AFL		N:0			0		
	<b>REF: AMM 52-30-01</b>			N:0			0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
520015	EMERGENGY 6 SERIE EXIT								
52.060	552.05.12.009 401 REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
523006	CARGO DOOR GAS STRUT								
	5523012427 NSN REF: AMM 52-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2020 3687:33 3021		

## CHAPTER 53 FUSELAGE

+ 53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3700:03 3030		
+ 53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS AS FAR AS POSSIBLE WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			3700:03 3030		
+ 53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			3576:24 2920		
+ 53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			3576:24 2920		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS							
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC	N/A						
		AFL							
+ 53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: AMM 53-20-02	AFL					3030		
+ 53-00/351	EDDY CURRENT INSPECTION UPPER LONGERONS FRAME 10								
		MOS							
<b>AIRWORTHINESS</b>	REF: AMM 53-10-06	HRS/MSC	32500					32500	
		AFL	42000					42000	
+ 53-00/352	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 10 TO 16								
		MOS							
<b>AIRWORTHINESS</b>	REF: AMM 53-10-00	HRS/MSC	32500					32500	
		AFL	42000					42000	
+ 53-00/353	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 16 TO 36								
		MOS							
<b>AIRWORTHINESS</b>	REF: AMM 53-20-00	HRS/MSC	32500					32500	
		AFL	42000					42000	
+ 53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43								
		MOS							
<b>AIRWORTHINESS</b>	REF: AMM 53-30-00	HRS/MSC	32500					32500	
		AFL	42000					42000	
+ 53-00/355	EXAMINE - ANTENNA STRUCTURE								
		MOS							
<b>AIRWORTHINESS</b>	REF: AMM 53-00-00	HRS/MSC	32500					32500	
		AFL	42000					42000	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-00-00</b>	HRS/MSC AFL	28300 37000					28300 37000	
+ 53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-00-00</b>	HRS/MSC AFL	32500 42000					32500 42000	
+ 53-00/359	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 WING ATTACHMENTS	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-00-03</b>	HRS/MSC AFL	30000 39000					30000 39000	
+ 53-00/360	EDDY CURRENT INSPECTION - FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 53-20-02</b>	HRS/MSC AFL	30000 39000					30000 39000	
+ 53-00/361	EDDY CURRENT INSPECTION FRAMES 41 AND 43 STABILIZER ATTACHMENT	MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC AFL	32500 42000					32500 42000	
+ 53-00/419	EDDY CURRENT INSPECTION FRAME 40	MOS					23-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE	MOS					21-MAY-2003		
53.010 <b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC AFL	20000 27000				0 0	20000 27000	
+ 53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)	MOS	48	+10%/-10%			28-MAY-2019	28-APR-2023	21-SEP-2023
53.030 <b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC AFL	4000	+10%/-10%	-30		3363:06 2694	7363:06	7763:06

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040		MOS	48	+10%/-10%		-30	28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	REF: GENERIC NO REF	AFL					2694		
+ 53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070		MOS	48	+10%/-10%		-30	28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	REF: GENERIC NO REF	AFL					2694		
+ 53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%		-30	28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	REF: GENERIC NO REF	AFL					2694		
+ 53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%		-30	28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	REF: GENERIC NO REF	AFL					2694		
530005	FUS ASPC12 10 SERIE A T-1/2 ASSY								
53.080	553.05.12.110	MOS					23-MAY-2003		
	401	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
<b>CHAPTER 55</b>	<b>STABILIZERS</b>								
270030	FIN ASSY								
	555.30.12.037	MOS					23-MAY-2003		
	401	HRS/MSC	O/C				0		
	REF: AMM 55-30-01	AFL					0		
+ 55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE (								
		MOS					21-MAY-2003		
		HRS/MSC	20000				0	<b>20000</b>	
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	AFL	27000				0	<b>27000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)	MOS							
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC AFL	N/A						
+ 55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: AMM 55-00-00	AFL					3030		
+ 55-10/415	HORIZONTAL STABILIZER								
	555.10.12.037	MOS		N:0			23-MAY-2003		
	410	HRS/MSC	25000	N:0			0	<b>25000</b>	
<b>LIFE LIMIT</b>	REF: AMM 55-10-01	AFL	30000	N:0			0	<b>30000</b>	
+ 55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	48	+10%/-10%		-30	28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	REF: GENERIC NO REF	AFL					2694		
+ 55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	48	+10%/-10%		-30	28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	REF: GENERIC NO REF	AFL					2694		
+ 55-20/362	EXAMINE LEFT ELEVATOR								
		MOS							
		HRS/MSC	32500					<b>32500</b>	
<b>AIRWORTHINESS</b>	REF: AMM 55-20-00	AFL	42000					<b>42000</b>	
+ 55-20/362	EXAMINE RIGHT ELEVATOR								
		MOS							
		HRS/MSC	32500					<b>32500</b>	
<b>AIRWORTHINESS</b>	REF: AMM 55-20-00	AFL	42000					<b>42000</b>	



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-01</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-20/368	EDDY CURRENT INSPECTION - LEFT ELEVATOR HINGES								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-01</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT ELEVATOR HINGES								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-20-01</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. IF CRACKS ARE FOUND FOR REPAIR PROCEDURE						PKG		
	PKG 17	MOS	12	+10%/-10%				10-FEB-2021	
		HRS/MSC	300	+10%/-10%				3700:03	
	<b>REF:</b>	AFL						3030	
+ 55-30/199 (s)	EXAMINE VERTICAL STABILIZER REAR SPAR STRAP AND LOWER AFT FAIRING SHEAR PLATE (PRE SB 55-002) IF WEAR IS FOUND REFER TO SB 55-002.						PKG		
	PKG 17	MOS	12	+10%/-10%				10-FEB-2021	
		HRS/MSC	300	+10%/-10%				3700:03	
	<b>REF:</b> GENERIC NO REF	AFL						3030	
+ 55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 20	MOS	12	+10%/-10%				10-FEB-2021	
		HRS/MSC	1200	+10%/-10%				3700:03	
	<b>REF:</b> GENERIC NO REF	AFL						3030	
+ 55-30/369	EXAMINE - VERTICAL STABILIZER								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 55-30-00</b>	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-00-00	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-30-02	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-30/420	EDDY CURRENT INSPECTION VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
		MOS					23-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-30-03	HRS/MSC	32500				0	<b>32500</b>	
		AFL	42000				0	<b>42000</b>	
+ 55-40/373	EXAMINE - RUDDER								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-40-00	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-40-05	HRS/MSC	32500					<b>32500</b>	
		AFL	42000					<b>42000</b>	
+ 55-40/410	EXAMINE RUDDER TRIM TAB								
		MOS					23-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-40-04	HRS/MSC	32500				0	<b>32500</b>	
		AFL	42000				0	<b>42000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55CUS01	SPECIAL INSPECTION FOR HORIZONTAL STABILIZER BOLTS P/N 555.10.12.139 REMOVAL AND INSPECTION FOR SIGNS OF CORROSION. CLEANING, CORROSION TREATMENT / REPLACEMENT OF BOLTS AS REQUIRED. INSTALLATION OF BOLTS AFTER INSPECTION								
	REF:	MOS HRS/MSC - AFL						28-MAY-2019 3363:06 2694	

## CHAPTER 56 WINDOWS

+ 56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 17	MOS	12	+10%/-10%				10-FEB-2021	
	REF: AMM 56-00-00	HRS/MSC AFL	300	+10%/-10%				3700:03 3030	
56-11/14	REPLACE LEFT HAND WINDSHEILD ASSEMBLY (INNER LAMINATION CRACKED)								
	959.81.10.107	MOS							
	02200H1565	HRS/MSC	A/R						
	REF: GENERIC NO REF	AFL							
56-11/14	REPLACE RIGHT HAND WINDSHEILD ASSEMBLY (INNER LAMINATION CRACKED)								
	959.81.10.108	MOS							
	02179H9288	HRS/MSC	A/R						
	REF: GENERIC NO REF	AFL							
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)								
	959.81.10.107	MOS							
	02200H1565	HRS/MSC	A/R						
	REF: GENERIC NO REF	AFL							
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)								
	959.81.10.108	MOS							
	02179H9288	HRS/MSC	A/R						
	REF: GENERIC NO REF	AFL							
+ 56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS								
		MOS	120	+6m/-6m				15-MAR-2013	15-MAR-2023
56.100		HRS/MSC	11000	+500/-500				2424:21	13424:21
	REF: AMM 56-11-02	AFL							15-SEP-2023 13924:21

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-11/378	EXAMINE WITH WINDSHIELD AND SIDE WINDOWS REMOVED - WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS								
		MOS							
		HRS/MSC	32500					32500	
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	AFL	42000					<b>42000</b>	
56-14/517	COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND								
	PKG 20	MOS	12				10-FEB-2021	<b>10-FEB-2022</b>	
		HRS/MSC	1200				3700:03	<b>4900:03</b>	
	<b>REF:</b> GENERIC NO REF	AFL					3030		
+ 56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	<b>REF:</b> AMM 56-00-00	AFL					3030		
560015	SIDE,LH WINDOW								
	959.81.10.111	MOS			N:0		23-MAY-2003		
56.090	02173H8726	HRS/MSC	O/C		N:0		0		
	<b>REF:</b> AMM 56-11-02	AFL			N:0		0		
560020	SIDE,RH WINDOW								
	959.81.10.112	MOS			N:0		23-MAY-2003		
56.090	02177H9043	HRS/MSC	O/C		N:0		0		
	<b>REF:</b> AMM 56-11-02	AFL			N:0		0		
560025	RH NO 1 CABIN WINDOW								
	556.20.12.029	MOS			N:0		23-MAY-2003		
56.060	3196	HRS/MSC	O/C		N:0		0		
	<b>REF:</b> AMM 56-20-01	AFL			N:0		0		
560030	RH NO 2 CABIN WINDOW								
	556.20.12.029	MOS			N:0		23-MAY-2003		
56.060	3199	HRS/MSC	O/C		N:0		0		
	<b>REF:</b> AMM 56-20-01	AFL			N:0		0		
560035	RH NO 3 CABIN WINDOW								
	556.20.12.029	MOS			N:0		23-MAY-2003		
56.070	3217	HRS/MSC	O/C		N:0		0		
	<b>REF:</b> AMM 56-20-01	AFL			N:0		0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560040	RH NO 4 CABIN WINDOW								
56.070	556.20.12.029 3218 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	556.20.12.029 3220 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	556.20.12.029 3221 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	556.20.12.029 3223 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
560060	LH NO 3 CABIN WINDOW								
56.050	556.20.12.029 3224 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	556.20.12.029 3226 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
560070	DV-WINDOW ASSY								
56.030	556.14.12.091 2193H1015 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
561010	LEFT HAND WINDSHEILD ASSEMBLY								
56.010	959.81.10.107 02200H1565 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
<b>AIRWORTHINESS</b>									

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561011	RIGHT HAND WINDSHEILD ASSEMBLY								
	959.81.10.108	MOS		N:0			23-MAY-2003		
56.010	02179H9288	HRS/MSC	O/C	N:0			0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 56-11-01</b>	AFL		N:0			0		
<b>CHAPTER 57 WINGS</b>									
+ 57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
		MOS					21-MAY-2003		
57.010		HRS/MSC	20000				0	<b>20000</b>	
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL	27000				0	<b>27000</b>	
+ 57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
		MOS					21-MAY-2003		
57.010		HRS/MSC	20000				0	<b>20000</b>	
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL	27000				0	<b>27000</b>	
+ 57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	<b>REF: GENERIC NO REF</b>	AFL					3030		
+ 57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG		
	PKG 21	MOS	24	+10%/-10%			06-MAR-2020		
		HRS/MSC	2400	+10%/-10%			3576:24		
	<b>REF: GENERIC NO REF</b>	AFL					2920		
+ 57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	<b>REF: GENERIC NO REF</b>	AFL					3030		
+ 57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	<b>REF: GENERIC NO REF</b>	AFL					3030		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS							
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC	N/A						
		AFL							
+ 57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS							
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC	N/A						
		AFL							
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-00-00</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-00-00</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 57-00/380	EDDY CURRENT INSPECTION - WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT	MOS							
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	30000					<b>30000</b>	
		AFL	39000					<b>39000</b>	
+ 57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000					<b>25000</b>	
		AFL	30000					<b>30000</b>	
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000					<b>25000</b>	
		AFL	30000					<b>30000</b>	
+ 57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	25000					<b>25000</b>	
		AFL	30000					<b>30000</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC AFL	25000 30000					25000 30000	
+ 57-00/384	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-05</b>	HRS/MSC AFL	25000 30000					25000 30000	
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-05</b>	HRS/MSC AFL	25000 30000					25000 30000	
+ 57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC AFL	25000 30000					25000 30000	
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC AFL	25000 30000					25000 30000	
+ 57-00/412	EXAMINE WING TIPS	MOS					23-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-33-00</b>	HRS/MSC AFL	32500 42000				0 0	32500 42000	
+ 57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES	MOS					23-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-01</b>	HRS/MSC AFL	25000 30000				0 0	25000 30000	
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					23-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-01</b>	HRS/MSC AFL	25000 30000				0 0	25000 30000	



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					21-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	16000				0		<b>16000</b>
		AFL	22500				0		<b>22500</b>
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					21-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-20-10</b>	HRS/MSC	16000				0		<b>16000</b>
		AFL	22500				0		<b>22500</b>
+ 57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	48	+10%/-10%			28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
57.020		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	<b>REF: GENERIC NO REF</b>	AFL			-30		2694		
+ 57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)	MOS	48	+10%/-10%			28-MAY-2019	<b>28-APR-2023</b>	21-SEP-2023
57.030		HRS/MSC	4000	+10%/-10%			3363:06	<b>7363:06</b>	7763:06
	<b>REF: GENERIC NO REF</b>	AFL			-30		2694		
+ 57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED	MOS	120	+6m/-6m			15-MAR-2013	<b>15-MAR-2023</b>	15-SEP-2023
57.040		HRS/MSC	11000	+500/-500			2424:21	<b>13424:21</b>	13924:21
	<b>REF: AMM 57-00-00</b>	AFL							
+ 57-60/393	EXAMINE LEFT WING AILERON	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-60-00</b>	HRS/MSC	32500						<b>32500</b>
		AFL	42000						<b>42000</b>
+ 57-60/393	EXAMINE RIGHT WING AILERON	MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 57-60-00</b>	HRS/MSC	32500						<b>32500</b>
		AFL	42000						<b>42000</b>
+ 57-60/411	EXAMINE AILERON TRIM TAB	MOS					23-MAY-2003		
		HRS/MSC	32500				0		<b>32500</b>
	<b>REF: AMM 57-60-04</b>	AFL	42000				0		<b>42000</b>

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
570010	AILERON RH 10A SERIE ASSY									
57.050	557.05.12.012 415 REF: AMM 57-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
570015	WING RE 10A SERIE STRUCTURE									
57.070	557.05.12.128 408 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
570025	AILERON LH 10A SERIE ASSY									
57.050	557.05.12.011 414 REF: AMM 57-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
570035	WING LE 10A SERIE STRUCTURE									
57.070	557.05.12.127 408 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0			
<b>CHAPTER 61 PROPELLERS/PROPULSORS</b>										
+ 61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG			
	<b>CMT ITEM</b>									
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021			
		HRS/MSC	1200	+10%/-10%			3700:03			
	REF: GENERIC NO REF	AFL					3030			
61PR1	NO. 1 PROPELLER									
61.PR1	MTV-27-1-N-C-F-R(P) 150403 REF: AMM 61-10-01	MOS HRS/MSC AFL	PP/C	N:0 N:0			04-DEC-2015 2873:15 2304			
<b>ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200</b>										
+ 612010	NO. 1 ENGINE - PROPELLER GOVERNOR									
	3049558-01	MOS					28-MAY-2019			
	13144006	HRS/MSC	3500	+500	N:198 O:0 N:3363:06 O:0		3363:06	(6863:06) 6863:06	7363:06	
OVERHAUL	REF: EMM 61-20-00	ENC			N:2694 O:0		2694			

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 612020	NO. 1 ENGINE - OVERSPEED GOVERNOR 3037685 13343520 REF: EMM 61-20-00	MOS HRS/MSC ENC	3500	+500			28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7363:06
OVERHAUL									
PROPELLER NO. 1 Model : MTV-27-1-N-C-F-R(P)/CFR260-65A Serial # 150403 Part # MTV-27-1-N-C-F-R(P)/CFR260-65A									
+ 610010	NO. 1 PROPELLER - OVERHAUL	MOS HRS/MSC	72 4000	+30d +50			04-DEC-2015 0	04-DEC-2021 (4000) 6873:15	03-JAN-2022 4050
OVERHAUL REF: GENERIC NO REF									
+ 610100	NO. 1 PROPELLER - ACCOMPLISH MT PROP ICA INSPECTION 150/ANNUAL	MOS HRS/MSC	12 300	+10%/-10% +10%/-10%		24	10-FEB-2021 826:48	06-MAR-2022 (1126:48) 4000:03	12-APR-2022 1156:48
REF: OMM 61-00-83									
610400	NO. 1 PROPELLER - PERFORM PROPELLER BALANCE	MOS HRS/MSC	A/R						
REF: GENERIC NO REF									
611501	NO. 1 PROPELLER - NO. 1 BLADE CFR260-65A AGC-56626 REF: GENERIC NO REF	MOS HRS/MSC	O/C		N:0 N:0		13-MAY-2015 0		
611502	NO. 1 PROPELLER - NO. 2 BLADE CFR260-65A AGC-56627 REF: GENERIC NO REF	MOS HRS/MSC	O/C		N:0 N:0		13-MAY-2015 0		
611503	NO. 1 PROPELLER - NO. 3 BLADE CFR260-65A AGC-56628 REF: GENERIC NO REF	MOS HRS/MSC	O/C		N:0 N:0		13-MAY-2015 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
611504	NO. 1 PROPELLER - NO. 4 BLADE CFR260-65A AGC-56629 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0				13-MAY-2015 0	
611505	NO. 1 PROPELLER - NO. 5 BLADE CFR260-65A AGC-56630 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0				13-MAY-2015 0	
+ 617010	NO. 1 PROPELLER - SEALS (IF STORED FOR LONGER THAN 24 MONTHS) REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC	A/R						
+ 618010	NO. 1 PROPELLER - INSPECTION TEAR-DOWN REF: GENERIC NO REF	MOS HRS/MSC	N/A						
+ 619010	NO. 1 PROPELLER - BETA/ OIL TRANSFER TUBE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC	N/A						
<b>CHAPTER 71 POWER PLANT</b>									
+ 71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER PKG 19 71.010 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%				PKG 10-FEB-2021 3700:03 3030	
+ 71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE PKG 19 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%				PKG 10-FEB-2021 3700:03 3030	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/106	CLEAN OIL PRESSURE TRANSDUCER ELECTRICAL CONNECTOR								
71.020		MOS							
	REF: AMM 71-00-03	HRS/MSC	A/R						
		AFL							
+ 71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 19	MOS	12	+10%/-10%				10-FEB-2021	
	REF: AMM 71-00-03	HRS/MSC	600	+10%/-10%				3700:03	
		AFL						3030	
+ 71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	PN	MOS			N:0			21-MAY-2003	
	SN-UNKNOWN	HRS/MSC	20000		N:0			0	20000
<b>AIRWORTHINESS</b>	REF: AMM 71-00-05	AFL	27000		N:0			0	27000
+ 71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, NUTS AND WASHERS								
71.050		MOS						21-MAY-2003	
	REF: AMM 71-00-04	HRS/MSC	11000					0	11000
<b>AIRWORTHINESS</b>		AFL						0	
+ 71-00/204 (s)	DO A POST INSPECTION GROUND RUN TEST AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
	REF: AMM 71-00-00	HRS/MSC	A/R					3700:03	
		AFL						3030	
+ 71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 20	MOS	12	+10%/-10%				10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%				3700:03	
		AFL						3030	
+ 71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS)						PKG		
	PKG 17	MOS	12	+10%/-10%				10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%				3700:03	
		AFL						3030	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/287 (s)	DO AN INSPECTION POWER PLANT GROUND RUN AS NECESSARY - NOTE DEFECTS. NOTE: A PRE INSPECTION GROUND RUN IS NOT A PRE-REQUISITE BUT MAY BE USEFUL TO DETERMINE ANY REPAIR WORK NEEDED TO MAINTAIN THE AIRWORTHINESS OF THE AIRCRAFT						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
	REF: AMM 71-00-00	HRS/MSC	A/R					3700:03	
		AFL						3030	
+ 71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. IF CRACKED, BLISTERED OR FLAKING PAINT IS FOUND ON THE MOUNTING FRAME						PKG		
	PKG 20	MOS	12	+10%/-10%				10-FEB-2021	
	REF:	HRS/MSC	1200	+10%/-10%				3700:03	
		AFL						3030	
+ 71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0				28-MAY-2019	
71.063	11393	HRS/MSC	3500	+10%/-10%	N:0	136:5		3363:06	7000 7350
						4			
OVERHAUL	REF: AMM 71-00-01	AFL		N:0				2694	
+ 71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0				28-MAY-2019	
71.064	11390	HRS/MSC	3500	+10%/-10%	N:0	136:5		3363:06	7000 7350
						4			
OVERHAUL	REF: AMM 71-00-01	AFL		N:0				2694	
+ 71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0				28-MAY-2019	
71.061	11397	HRS/MSC	3500	+10%/-10%	N:0	136:5		3363:06	7000 7350
						4			
OVERHAUL	REF: AMM 71-00-01	AFL		N:0				2694	
+ 71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0				28-MAY-2019	
71.060	11393	HRS/MSC	3500	+10%/-10%	N:0	136:5		3363:06	7000 7350
						4			
OVERHAUL	REF: AMM 71-00-01	AFL		N:0				2694	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
	9448121409	MOS		N:0			28-MAY-2019		
71.062	11386	HRS/MSC	3500	+10%/-10%	N:0	136:5	3363:06	7000	7350
						4			
<b>OVERHAUL</b>	<b>REF: AMM 71-00-01</b>	AFL		N:0			2694		
+ 71-00/401	MAGNETIC PARTICLE INSPECT - ENGINE MOUNT								
		MOS							
		HRS/MSC	26600					26600	
<b>AIRWORTHINESS</b>	<b>REF: AMM 71-00-05</b>	AFL	35000					35000	
71-00/476 (s)	REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
		HRS/MSC	A/R					3700:03	
	<b>REF: GENERIC NO REF</b>	AFL						3030	
+ 71-10/207 (s)	OPEN AND EXAMINE ENGINE COWLINGS ENG 43AL AND ENG 43AR AND SPECIFICALLY THE CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
		HRS/MSC	A/R					3700:03	
	<b>REF: GENERIC NO REF</b>	AFL						3030	
+ 71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 15 ,16,17,18,19,20,21	MOS						10-FEB-2021	
		HRS/MSC	A/R					3700:03	
	<b>REF: GENERIC NO REF</b>	AFL						3030	
71-10/476	REVIEWED AND COMPLIED WITH AS NECESSARY, P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS								
		MOS						23-MAY-2003	
		HRS/MSC	A/R					0	
	<b>REF:</b>	AFL						0	
710005	UPPER LH ENGINE VIBRATION ISOLATOR								
	571.20.12.106	MOS		N:0				23-MAY-2003	
71.070	0888	HRS/MSC	O/C	N:0				0	
	<b>REF: GENERIC NO REF</b>	AFL		N:0				0	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR								
71.080	571.20.12.106 0904 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
710025	UPPER RH ENGINE VIBRATION ISOLATOR								
71.090	571.20.12.106 0893 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
710035	LOWER LH ENGINE VIBRATION ISOLATOR								
71.100	571.20.12.106 0880 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
710045	LOWER RH ENGINE VIBRATION ISOLATOR								
71.110	571.20.12.106 0891 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
71CUS01	ENGINE MOUNT								
	571.20.12.036 405 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAY-2003 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	3042200 PCE-PR0368 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C	N:0 N:0 N:0			26-MAY-2003 0 0		
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200									
+ 710011	NO. 1 ENGINE - OVERHAUL								
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7063:06



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE PKG 2 REF: EMM 72-30-05	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960		
+ 710021	NO. 1 ENGINE - HOT SECTION INSPECTION CMT ITEM REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			28-MAY-2019 3363:06 2694	(5113:06) 5113:06	5363:06
+ 710031	NO. 1 ENGINE - BORESCOPE HOT SECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	400	+10%/-10%			06-MAR-2020 3576:24 2854	(3976:24) 3976:24	4016:24
+ 710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES REF: EMM 72-00-00	MOS HRS/MSC ENC	4000	+100/-100			30-NOV-2002 0 0	(4000) 4000	4100
+ 710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	6 300	+10%/-10% +10%/-10%			10-FEB-2021 3700:03 2960	10-AUG-2021 (4000:03) 4000:03	28-AUG-2021 4030:03
+ 710051	NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	6 300	+10%/-10% +10%/-10%			10-FEB-2021 3700:03 2960	10-AUG-2021 (4000:03) 4000:03	28-AUG-2021 4030:03
+ 710052	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	A/R				28-MAY-2019 3363:06 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710053	NO. 1 ENGINE - EXTERNAL ENGINE WASH	MOS	6	+10%/-10%			10-FEB-2021	<b>10-AUG-2021</b>	28-AUG-2021
	REF: EMM 71-00-00	HRS/MSC	300	+10%/-10%			3700:03	<b>(4000:03) 4000:03</b>	4030:03
		ENC					2960		
+ 710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS	12	+10%/-10%	-5		10-FEB-2021	<b>05-FEB-2022</b>	11-MAR-2022
	REF: EMM 72-00-00	HRS/MSC	300	+10%/-10%			3700:03	<b>(4000:03) 4000:03</b>	4030:03
		ENC					2960		
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION						PKG		
	PKG 2	MOS					10-FEB-2021		
	REF: EMM 71-00-00	HRS/MSC	300	+10%/-10%			3700:03		
		ENC					2960		
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE	MOS					20-FEB-2018		
	REF: EMM 72-00-00	HRS/MSC	A/R				3195:20		
		ENC					2528		

**CHAPTER 72 ENGINE**

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200

+ 720010	NO. 1 ENGINE - GAS GENERATOR MODULE	MOS					28-MAY-2019		
	3123221-01	HRS/MSC	3500	+200	N:198 O:0		3363:06	<b>(6863:06) 6863:06</b>	7063:06
	26L194	ENC			N:3363:06 O:0		2694		
	OVERHAUL	REF: See Workcard			O:0				
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL	MOS					30-NOV-2002		
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP	MOS					30-NOV-2002		
	REF: EMM 72-60-00	HRS/MSC	A/R				0		
		ENC					0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
	REF: GENERIC NO REF								
+ 720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
	REF: GENERIC NO REF								
+ 720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
	REF: GENERIC NO REF								
+ 720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
	REF: GENERIC NO REF								
+ 720087	NO. 1 ENGINE - REGULAR OPERATION AS ALTERNATIVE TO PRESERVATION OF INACTIVE ENGINES	MOS HRS/MSC ENC	A/R				30-NOV-2002 0 0		
	REF: EMM 72-00-00								
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS	MOS HRS/MSC ENC	A/R				30-NOV-2002 0 0		
	REF: EMM 72-11-00								
+ 722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
	REF: See Workcard								
+ 722011	NO. 1 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR 3037719	MOS HRS/MSC ENC	O/C				30-NOV-2002 0 0		
	SN-UNKNOWN REF: GENERIC NO REF								

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION						PKG		
	PKG 2	MOS						10-FEB-2021	
		HRS/MSC	300	+10%/-10%				3700:03	
	REF: EMM 72-20-00	ENC						2960	
+ 723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR								
	3039001	MOS			N:0			30-NOV-2002	
	TX1A2122	HRS/MSC			N:0			0	
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	ENC	24000		N:0			0	<b>(24000) 24078</b>
+ 723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT								
	3043063	MOS			N:0			30-NOV-2002	
	73A506	HRS/MSC			N:0			0	
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	ENC	24000		N:0			0	<b>(24000) 24078</b>
+ 723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION						PKG		
	PKG 2	MOS						10-FEB-2021	
		HRS/MSC	300	+10%/-10%				3700:03	
	REF: EMM 72-30-04	ENC						2960	
+ 723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR								
	3040952	MOS			N:0			30-NOV-2002	
	TX1A2580	HRS/MSC			N:0			0	
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	ENC	24000		N:0			0	<b>(24000) 24078</b>
+ 723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS						PKG		
	PKG 2	MOS						10-FEB-2021	
		HRS/MSC	300	+10%/-10%				3700:03	
	REF: See Workcard	ENC						2960	
+ 723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR								
	3040933	MOS			N:0			30-NOV-2002	
	65B295	HRS/MSC			N:0			0	
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	ENC	24000		N:0			0	<b>(24000) 24078</b>

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 83B227	MOS HRS/MSC		N:0 N:0			30-NOV-2002 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	24000	N:0			0	<b>(24000) 24078</b>	
+ 723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 6H418	MOS HRS/MSC		N:0 N:0			30-NOV-2002 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	24000	N:0			0	<b>(24000) 24078</b>	
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION	MOS HRS/MSC A/R					30-NOV-2002 0		
<b>UNSCHEDULED MAINTENANCE CHECK</b>	<b>REF: See Workcard</b>	ENC					0		
+ 725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 A001A5FH	MOS HRS/MSC		N:0 N:0			30-NOV-2002 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	8000	N:0			0	<b>(8000) 8078</b>	
+ 725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS HRS/MSC	5000						
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC						<b>(5000) 5000 M</b>	
+ 725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 2	MOS HRS/MSC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
	<b>REF: EMM 72-50-05</b>	ENC							
+ 725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312 A001A837	MOS HRS/MSC		N:0 N:0			30-NOV-2002 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 15078</b>	
+ 725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313 A001A784	MOS HRS/MSC		N:0 N:0			30-NOV-2002 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 15078</b>	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO. 1 COMPRESSOR TURBINE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	6000	N:0 N:0 N:0			30-NOV-2002 0 0	(6000) 6000	
725122	NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE 3044183-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	H/T	O:0 O:0 O:0			03-MAY-2019 3363:42 2673		
+ 726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	N:198 O:0 N:3363:06 O:0 N:2694 O:0	+200		28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7063:06
726030	NO. 1 ENGINE - ELECTRICAL FILLER CAP AND INDICATOR, OIL-LEVEL 3045457-01 AB0342 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				03-MAY-2019 3363:42 2673		
72CUS01	NO. 1 ENGINE - NO. 1 OPTION BEARING 3028004 BB0027998 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS02	NO. 1 ENGINE - NO. 2 OPTION BEARING 3028004 BB0028019 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS03	NO. 1 ENGINE - COMPRESSOR TURBINE STATOR OF ASSEMBLY 3040931CL0710 C0148 REF:	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-MAY-2019 3363:42 2673		
72CUS04	NO. 1 ENGINE - VANE RING POWER TURBINE 3040982CL01 LPRL01 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72CUS05	NO. 1 ENGINE - VANE RING TURBINE 3041123 K0108 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS06	NO. 1 ENGINE - POWER TURBINE STATOR HOUSING 3043706-01 0198GZ00143 REF:	MOS HRS/MSC ENC	O/C				03-MAY-2019 3363:42 2673		
72CUS07	NO. 1 ENGINE - SECOND STAGE GEAR REDUCTION RING 3045049-01 59E318 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS08	NO. 1 ENGINE - FRONT PROPELLER REDUCTION GEARBOX HOUSING ASSEMBLY 3045195-01 A00184RM REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS09	NO. 1 ENGINE - PROPELLER SHAFT 3048698-01 A0018NC8 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS10	NO. 1 ENGINE - TURBINE EXHAUST DUCT OF ASSEMBLY 3055331-01 A0019AWR REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS11	NO. 1 ENGINE - OUTER LINER COMBUSTION CHAMBER ASSEMBLY 3055657-01 22N176 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS12	NO. 1 ENGINE - ANNULAR BEARING BALL 3101647-01 FA0219651 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72CUS13	NO. 1 ENGINE - FLANGED ROLLER BEARING 3107500-01 FC120369 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS14	NO. 1 ENGINE - ROLLER FL 3.14 X 5.23 X.760 BEARING 3107504-01 FC121472 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS15	NO. 1 ENGINE - COUPLING POWER TURBINE 3107525-01 63E664 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS16	NO. 1 ENGINE - FIRST STAGE REDUCTION CARRIER 3107995-01 61E233 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS17	NO. 1 ENGINE - FIRST STAGE GEAR REDUCTION RING 3108308-01 61E626 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS18	NO. 1 ENGINE - FIRST STAGE REDUCTION SPLN ADAPTER 3108312-01 43W460 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS19	NO. 1 ENGINE - FIRST STAGE REDUCTION SUN GEAR 3108356-01 63E539 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS20	NO. 1 ENGINE - T5 NEGATIVE TERMINAL BUS BAR 3109239-01 NR05503 REF:	MOS HRS/MSC ENC	O/C				03-MAY-2019 3363:42 2673		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72CUS21	NO. 1 ENGINE - T5 POSITIVE TERMINAL BUS BAR 3109240-01 NR05477 REF:	MOS HRS/MSC ENC	O/C				03-MAY-2019 3363:42 2673		
72CUS22	NO. 1 ENGINE - POWER TURBINE SHAFT 3109251-01 72A250 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS23	NO. 1 ENGINE - NO. 1 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220547 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS24	NO. 1 ENGINE - NO. 2 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220548 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS25	NO. 1 ENGINE - NO. 3 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220549 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS26	NO. 1 ENGINE - NO. 4 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220550 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS27	NO. 1 ENGINE - NO. 5 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220553 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS28	NO. 1 ENGINE - NO. 6 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220554 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72CUS29	NO. 1 ENGINE - NO. 7 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220562 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS30	NO. 1 ENGINE - NO. 8 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220563 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS31	NO. 1 ENGINE - NO. 9 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220564 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS32	NO. 1 ENGINE - NO. 10 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220565 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS33	NO. 1 ENGINE - NO. 11 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220572 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS34	NO. 1 ENGINE - NO. 12 FLANGED ROLLER 94X1.65X47 BEARING 3112368-01 FA0220573 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS35	NO. 1 ENGINE - REAR COMPRESSOR HUB COUPLING 3112612-01 41W161 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
72CUS36	NO. 1 ENGINE - FLANGED ROLLER 1.181X2.8345X.743 BEARING BALL 3112696-03 FC121101 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72CUS37	NO. 1 ENGINE - SECOND STAGE REDUCTION SUN GEAR 3112772-01 63E518 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	
72CUS38	NO. 1 ENGINE - SECOND STAGE REDUCTION CARRIER 3112779-01 57E211 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	
72CUS39	NO. 1 ENGINE - 1.450X3.600X1.000 BEARING BALL 3113589-01 FA0216903 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	
72CUS40	NO. 1 ENGINE - POWER TURBINE COUPLING SHAFT 3113744-01 43W119 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	
72CUS41	NO. 1 ENGINE - INNER LINER COMBUSTION CHAMBER ASSEMBLY 3116790-01 22N414 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	
72CUS42	NO. 1 ENGINE - STUB COMPRESSOR ROTOR SHAFT 3120663-01 71A563 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	
72CUS43	NO. 1 ENGINE - NO. 1 FIRST STAGE REDUCTION 51TEE PLANET GEAR 3120848-01 55E857 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	
72CUS44	NO. 1 ENGINE - NO. 2 FIRST STAGE REDUCTION 51TEE PLANET GEAR 3120848-01 55E860 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				30-NOV-2002 0 0	

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72CUS45	NO. 1 ENGINE - NO. 3 FIRST STAGE REDUCTION 51TEE PLANET GEAR 3120848-01 55E862 REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			30-NOV-2002 0 0		
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200									
+ 731010	NO. 1 ENGINE - FUEL PUMP 3040760 006239 REF: EMM 73-10-02	MOS HRS/MSC ENC	3500	N:198 O:0 N:3363:06 O:0 N:2694 O:0			28-MAY-2019 3363:06 2694	(6863:06) 6863:06	
<b>OVERHAUL</b>									
+ 731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) REF: See Workcard	MOS HRS/MSC ENC	N/A				28-MAY-2019 3363:06 2694		
+ 731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM) CMT ITEM REF: EMM 73-11-05	MOS HRS/MSC ENC	400	+10%/-10%			06-MAR-2020 3576:24 2854	(3976:24) 3976:24	4016:24
+ 731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3055748-01 C50418 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+500	N:198 O:0 N:3363:06 O:0 N:2694 O:0		28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7363:06
<b>OVERHAUL</b>									
+ 731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
+ 731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A						

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN <b>CMT ITEM</b> 3040760 006239 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			28-MAY-2019 3363:06 2694	(3963:06) 3963:06	4023:06
+ 731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 2 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960		
+ 731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 006239 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				28-MAY-2019 3363:06 2694		
+ 731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				28-MAY-2019 3363:06 2694		
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER <b>CMT ITEM</b> PN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			28-MAY-2019 3363:06 2694	(3963:06) 3963:06	4023:06
+ 731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960		
+ 731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA19164 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:198 O:0 N:3363:06 O:0 N:2694 O:0		28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7363:06

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731065	NO. 1 ENGINE - EXAMINE FILTER BOWL  REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			10-FEB-2021 3700:03 2960	(4000:03) 4000:03	4030:03
+ 731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 2151 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:198 O:0 N:3363:06 O:0 N:2694 O:0		28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7363:06
+ 731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960		
+ 731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-04 13358852 REF: EMM 73-20-00  <b>OVERHAUL</b>	MOS HRS/MSC ENC	3500	+500	N:198 O:0 N:3363:06 O:0 N:2694 O:0		28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7363:06
+ 731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960		
+ 731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF  <b>LIFE LIMIT</b>	MOS HRS/MSC ENC	4000		N:198 N:3363:06 N:2694		28-MAY-2019 3363:06 2694	(4000) 4000	
+ 731100	NO. 1 ENGINE - CLEAN P3 FILTER <b>CMT ITEM</b>  REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960	(4000:03) 4000:03	4030:03
+ 731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER <b>CMT ITEM</b> PN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T				28-MAY-2019 3363:06 2694		
+ 732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 2 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
+ 733020	NO. 1 ENGINE - REPLACE P3 FILTER <b>CMT ITEM</b> REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			03-MAY-2019 3363:42 2673	(4263:42) 4263:42	4353:42
+ 733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			10-FEB-2021 3700:03 2960	(4000:03) 4000:03	4030:03
<b>CHAPTER 74 IGNITION</b>									
+ 74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM <b>CMT ITEM</b> PKG 17 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 10-FEB-2021 3700:03 3030		
<b>ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200</b>									
+ 740010	NO. 1 ENGINE - IGNITION EXCITER 10-381550-4 17743C REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:74 O:0 N:938:45 O:0 N:2694 O:0		28-MAY-2019 3363:06 2694	(6863:06) 6863:06	7363:06
+ 740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	400	+10%/-10%			06-MAR-2020 3576:24 2854	(3976:24) 3976:24	4016:24

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION <b>CMT ITEM</b>	MOS					06-MAR-2020		
	REF: EMM 74-20-00	HRS/MSC ENC	400	+10%/-10%			3576:24 2854	(3976:24) 3976:24	4016:24
+ 742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION	MOS					06-MAR-2020		
	REF: EMM 74-20-00	HRS/MSC ENC	400	+10%/-10%			3576:24 2854	(3976:24) 3976:24	4016:24
<b>CHAPTER 75 AIR</b>									
ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200									
+ 750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE	MOS					28-MAY-2019		
	3123532-01 51A822 REF: EMM 75-30-00	HRS/MSC ENC	3500	+500	N:198 O:0 N:3363:06 O:0 N:2694 O:0		3363:06 2694	(6863:06) 6863:06	7363:06
<b>CHAPTER 76 ENGINE CONTROLS</b>									
+ 76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT						PKG		
	PKG 19 REF: GENERIC NO REF	MOS AFL	12	+10%/-10%			10-FEB-2021 3700:03 3030		
+ 76-00/211 (s)	MAKE SURE BETA SLIP RING CARBON BLOCK GAP IS NOT MORE THAN 0.01IN (0.25MM)						PKG		
	PKG 17 REF: GENERIC NO REF	MOS AFL	12	+10%/-10%			10-FEB-2021 3700:03 3030		
+ 76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT-CAUTION-DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE.						PKG		
	<b>CMT ITEM</b> PKG 16 REF: AMM 76-10-00	MOS AFL	300	+10%/-10%			10-FEB-2021 3700:03 3030		



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT POWER CONTROL - OPERATIONAL TEST. MANUAL OVERRIDE						PKG		
	<b>CMT ITEM</b>								
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: See Workcard	AFL					3030		
+ 76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT						PKG		
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES								
	<b>CMT ITEM</b>								
76.010		MOS	12	+1m/-1m		-4	10-FEB-2021	<b>06-FEB-2022</b>	06-MAR-2022
		HRS/MSC	3000	+10%/-10%			3700:03	<b>6700:03</b>	7000:03
	REF: AMM 76-10-02	AFL					3030		
760015	MANUAL OVERRIDE CABLE ASSY.								
	941.94.11.417	MOS					23-MAY-2003		
76.020	20030007	HRS/MSC	O/C				0		
	REF: AMM 76-20-04	AFL					0		
760020	CONDITION CABLE ASSY.								
	941.94.11.418	MOS					23-MAY-2003		
76.030	20030003	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
760025	POWER CONTROL CABLE ASSY.								
	941.94.11.419	MOS					23-MAY-2003		
76.040	20030001	HRS/MSC	O/C				0		
	REF: AMM 76-10-04	AFL					0		

**ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200**

+ 761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES								
		MOS					10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03	<b>(4000:03) 4000:03</b>	4030:03
	REF: EMM 72-00-00	ENC					2960		

**CHAPTER 77 ENGINE INDICATING**

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 77-00/213 (s)	OPERATIONAL TEST ENGINE INSTRUMENT SYSTEM PKG 17	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: See Workcard	HRS/MSC AFL	300	+10%/-10%			3700:03 3030		
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER 975.21.15.206	MOS		N:0			23-MAY-2003		
77.010	6479-2-159 REF: AMM 77-40-03	HRS/MSC AFL	O/C	N:0 N:0			0 0		
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER 975.21.15.212	MOS		N:0			23-MAY-2003		
77.030	1623592 REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
770020	ACQ/DISPLAY UNIT 975.29.02.017	MOS		N:0			23-MAY-2003		
77.020	113 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		

**ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200**

771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS 3043825-01	MOS					03-MAY-2019		
	NR01394 REF: EMM 77-20-01	HRS/MSC ENC	O/C				3363:42 2673		
771020	NO. 1 ENGINE - T5 TERMINAL BLOCK 3108068-01	MOS					03-MAY-2019		
	NR09547 REF: EMM 77-20-01	HRS/MSC ENC	O/C				3363:42 2673		

**CHAPTER 78 EXHAUST**

+ 78-00/214 (s)	EXAMINE EXHAUST STUBS PKG 17	MOS	12	+10%/-10%			PKG	10-FEB-2021	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			3700:03 3030		

**CHAPTER 79 OIL**

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-00/215 (s)	EXAMINE OIL FILLER CAP/DIPSTICK. ENERGIZE AIRCRAFT ELECTRICAL SYSTEM. REMOVE FILLER CAP, EXAMINE AND MAKE SURE THE SEAL IS IN GOOD CONDITION. SET AND HOLD AIR/GROUND SWITCH TO GROUND AND MAKE SURE AFTER 60 SECONDS THE CAWS OIL QTY CAPTION COMES ON. INSTALL FILLER CAP AND MAKE SURE THE LOCKING MECHANISM OPERATES CORRECTLY.						PKG		
	<b>CMT ITEM</b>								
	PKG 19	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	600	+10%/-10%			3700:03		
	REF: AMM 24-00-00	AFL					3030		
+ 79-20/289 (s)	EXAMINE ENGINE OIL COOLER MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 20	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	1200	+10%/-10%			3700:03		
	REF: GENERIC NO REF	AFL					3030		
+ 79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM						PKG		
	<b>CMT ITEM</b>								
	PKG 17	MOS	12	+10%/-10%			10-FEB-2021		
		HRS/MSC	300	+10%/-10%			3700:03		
	REF: AMM 79-30-01	AFL					3030		
+ 79-20/43	OIL COOLER								
	968.32.14.102	MOS		O:0			28-MAY-2019		
79.010	T1030	HRS/MSC	3500	+10%/-10%	O:0	136:5	3363:06	7000	7350
						4			
<b>OVERHAUL</b>	REF: AMM 79-20-02	AFL		O:0			2694		
790005	TEMPERATURE BULB								
	975.11.20.101	MOS		N:0			23-MAY-2003		
79.020	109598	HRS/MSC	O/C	N:0			0		
	REF: AMM 79-30-03	AFL		N:0			0		
790020	PRESSURE,GAGE SWITCH								
	973.81.14.305	MOS		N:0			23-MAY-2003		
79.030	0409	HRS/MSC	O/C	N:0			0		
	REF: AMM 79-30-04	AFL		N:0			0		
790025	THERMAL ACTUATOR								
	978.73.01.002	MOS		N:0			23-MAY-2003		
79.040	0547	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

ENGINE NO. 1 Model : PT6A-67B Serial # PCE-PR0368 Part # 3042200

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS							
<b>DISCARD</b>	<b>REF: GENERIC NO REF</b>	HRS/MSC ENC	A/R						
+ 790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS	12	+30d/-10%			10-FEB-2021	<b>10-FEB-2022</b>	12-MAR-2022
	<b>REF: EMM 79-20-02</b>	HRS/MSC ENC	300	+10%/-10%			3700:03 2960	<b>(4000:03) 4000:03</b>	4030:03
+ 790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR	MOS	12	+1m/-1m			10-FEB-2021	<b>06-FEB-2022</b>	06-MAR-2022
	<b>CMT ITEM</b>	HRS/MSC ENC	600	+10%/-10%		-4	3700:03 2960	<b>(4300:03) 4300:03</b>	4360:03
	<b>REF: EMM 79-20-02</b>								
+ 790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT	MOS					28-MAY-2019		
	<b>CMT ITEM</b>	HRS/MSC ENC	900	+10%/-10%			3363:42 2673	<b>(4263:42) 4263:42</b>	4353:42
	<b>REF: EMM 79-20-02</b>								
+ 790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN	MOS					10-FEB-2021		
	<b>CMT ITEM</b>	HRS/MSC ENC	300	+10%/-10%			3700:03 2960	<b>(4000:03) 4000:03</b>	4030:03
	<b>REF: EMM 79-20-02</b>								
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN	MOS					20-FEB-2018		
	<b>REF: EMM 72-60-00</b>	HRS/MSC ENC	1000	+10%/-10%		76:55	3195:20 2528	<b>(4272:15) 4272:15</b>	4372:15
+ 790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE	MOS					13-JUN-2018		
	<b>REF: EMM 79-20-02</b>	HRS/MSC ENC	N/A				3293:41 2625		

# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING  REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				30-NOV-2002 0 0		
+ 790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS PKG 2  REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
+ 790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 2  REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 10-FEB-2021 3700:03 2960		
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER 975.21.15.214 6567-6-48 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		30-NOV-2002 0 0		

CHAPTER --	GENERAL								
25-CUS-01	PILOT LIFE VEST 63600-105 L3977198 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120		N:20		29-JUL-2019	01-OCT-2027	M
25-CUS-02	CO-PILOT LIFE VEST 63600-105 L3977164 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120		N:20		29-JUL-2019	01-OCT-2027	M
25-CUS-03	1 PAX SEAT LIFE VEST 63600-105 L3977165 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120		N:20		29-JUL-2019	01-OCT-2027	M



# Status Report

PC-12/45 S/N 498 (OH-MUG): 3734:55 HRS, 3080 AFL as of 16-May-2021

Owner: MUGABURU SL Operator: FLY 7 FINLAND OY

Report Date: 10-JUN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-CUS-04	2 PAX SEAT LIFE VEST 63600-105 L3977206 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120	N:20			29-JUL-2019	01-OCT-2027	M
25-CUS-05	3 PAX SEAT LIFE VEST 63600-105 L3977171 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120	N:20			29-JUL-2019	01-OCT-2027	M
25-CUS-06	4 PAX SEAT LIFE VEST 63600-105 L3977162 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120	N:20			29-JUL-2019	01-OCT-2027	M
25-CUS-07	5 PAX SEAT LIFE VEST 63600-105 L3977170 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120	N:20			29-JUL-2019	01-OCT-2027	M
25-CUS-08	6 PAX SEAT LIFE VEST 63600-105 L3977193 REF: Manufacture Date: 01-NOV-2017	MOS HRS/MSC AFL	120	N:20			29-JUL-2019	01-OCT-2027	M
25-CUS-09	7 PAX SEAT LIFE VEST 63600-105 L4652481 REF: Manufacture Date: 01-MAR-2019	MOS HRS/MSC AFL	120	N:4			29-JUL-2019	01-FEB-2029	M
25-CUS-10	8 PAX SEAT LIFE VEST 63600-105 L4652486 REF: Manufacture Date: 01-MAR-2019	MOS HRS/MSC AFL	120	N:4			29-JUL-2019	01-FEB-2029	M